

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 03 Jul 2024

Preliminary Advice

Insured Vehicle No	: SLV3250S		
TP Vehicle No	: SKS8653H	Accident Date	: 25/06/2024
Make	: MERCEDES-BENZ CLA180	Assignment Date	: 01/07/2024
Date of Inspection	: 02/07/2024	Est. Duration of Repair	: 2
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,182.40
Revised Amount	:S\$	2,353.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,353.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.