

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O in/s _____

of _____

Insured: _____

Policy: File

Claims File

Sum Insured Excess: _____

(Client's Record)

Make of Vehicle

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS 8653H Yr Regn: 2015, May

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz CLA180 1595

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 142514 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1173422N196545

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 02/07/24

Success United.

Date / Time

Action / Instruction

TP MS/B

COE Expiry

Estimate given during : Yes (✓)

1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Form:

Report Form / L.P.P. /

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Attention : Motor Claim Department
Contact : 68277888 Fax No. : 62257402

Estimate : TP24-063

Date : 01/07/2024
Vehicle Num. : SKS8653H
Make/Model : Mercedes CLA180-2015
Chassis/Eng# : WDD1173422N196545/27091030626168
Accident Date : 25/06/2024
Claim No. :
Reference :
Policy No. : 11428709

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Rear Bumper Assy <i>del</i>		1,630.00 ✓
2.	1	Rear Lower Bumper <i>at</i>		485.00 ✓
3.	1	Rear bumper chrome trim assy <i>ren</i>		590.00 +
4.	2	Rear Bumper Bracket L/R <i>ren</i>	158.00	316.00 +
5.	1	Rear Bumper Reinforcement		780.00 +
6.	1	Rear PDC parking sensor		235.00 +

List Total S\$:
10.00% Discount S\$:

4,036.00
403.60

3,632.40

1.	10	SPECIAL NETT ITEMS : Rear Bumper Clips <i>ren</i>	15.00	150.00 <i>50</i>
Special Nett Total S\$:				150.00

LABOUR :
To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident

To putty and respray painting on rear bumper and
rear boot lid.

Labour Total S\$:

600.00 *200*
800.00 *200*

1,400.00

Total S\$: 5,182.40
=====

pting
SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim
1/5 02/07/24
22 Days