

ASS. REC. BY: TaufikREF: CS/10524120191/Tv h3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

② OD/TP/WS/TP RES/LOD RES/EVA/INV/INV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. MPC24P00462800Claims No. DMPC2401713H/CT

Sum Insured: _____

Excess: \$0

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Est. or Market Value: 9115K

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT
CarineVeh No: SMN13608Yr Regn: 2019, 07Type: M.Crr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Lexus ES250c.c. 2487Colour: SilverA/C: Insured / Std / NI / NASp Reading: 58969T/Radio: Insured / Std / NI / NA

Eng No: _____

C.No: 3THB11B1702010082Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NI / SRIm / STD A/RIm orTyre Size: F: 235/45R18R: 235/45R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 11/12/2024D.O.I. 13/12/24Survey held at Borneo PandaDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFrt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/1/25

Taufikh confirmed final fig \$12,812.59 (Red 11, 863.80, 48%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Tlp: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

Rep. Format: _____

Lump Sum / L.B.I. / % _____



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Mr Neubronner Colin Michael 15 Leedon Heights #23-51 Singapore 266225 Mobile: 84991057			
			Document No. 0					
			Document Date 12/12/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXZA10R	AEZGB S1	15/07/2019	SMN1360B	0	25583	SMN1360B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHB11B1402010082		A25A5172534	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: MPC24P00462800 ACC DATE: 11.12.2024 TOW/DRIVE IN:TOWED IN EXCESS: DATE-IN: 11.12.2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						50 100.00
2	B	BP-LAB3 TO CUT, WELD PANELS ON ALL ACCIDENT AFFECTED PORTION, TO REPAIR, REPLACE PARTS ON ALL ACCIDENT DAMAGED PARTS						960 2304.00
3	B	BP-RES3 TO SPRAY PAINT ON FRONT AFFECTED PORTION OF VEHICLE						816 2448.00
4	B	BP-LAB3 TO REMOVE AND REPLACE RHS HEADLAMP. CHECK AND FOCUS HEADLIGHTS (NETT)						✓ 192.00
5	B	BP-LAB3 TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)						✓ 192.00
6	B	BP-MECH3 TO CONDUCT ADJUSTMENT ON FRONT WAVE RADAR SENSOR (NETT)						✓ 192.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Tanfikun 97495749 Not Authorise, Revent Ex: \$0 P/P Resurvey before paint tanfikun@lkkauto.com 13/12/24 @ 1145 Amount Due

Customer Copy

04 days



icape
J. Reg No. : 196700086Z
JST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Mr Neubronner Colin Michael 15 Leedon Heights #23-51 Singapore 266225 Mobile: 84991057			
			Document No. 0					
			Document Date 12/12/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXZA10R	AEZGB S1	15/07/2019	SMN1360B	0	25583	SMN1360B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHB11B1402010082		A25A5172534	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
7	B	BP-ECU3 TO RESET ECU AND REPROGRAMME (NETT)						✓ 192.00
8	Z	BP-MPS MERIMEN'S PROCESSING FEES						✓ 12.00
9	B	BP-MECH3 TO REMOVE AND REPLACE FRONT SENSOR WIRE HARNESS (NETT)						? 384.00
10	T	BP-MISC1 SHOULD THE VEHICLE IS DEEMED A TOTAL LOSS OR TOWED OUT BY THE INSURER / OWNER BEFORE REPAIR, A 6% FEE (CAPPED AT \$1000 EXCL. TOWING) APPLIES.						
11	T	BP-MISC1 THIS ALSO APPLIES IF THE POLICY ALLOWS REPAIR AT AN AUTHORIZED DEALER, BUT REPAIRS ARE NOT DONE AT OUR WORKSHOP DESPITE AN ESTIMATE, OR TOWING IS REDIRECTED						
12	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.						
13	1	L52618-33090 ABSORBER, FR BUMPER,			1.00	390.10	30.00	273.07
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy

J. Reg No. : 196700086Z
 JST Reg No. : MR-8500000-9
 No.2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Mr Neubronner Colin Michael 15 Leedon Heights #23-51 Singapore 266225 Mobile: 84991057
	Document No. 0	
	Document Date 12/12/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXZA10R	AEZGB S1	15/07/2019	SMN1360B	0	25583	SMN1360B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB11B1402010082	A25A5172534	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	2	L52611-33330 ABSORBER, FR BUMPER	1.00	155.70	30.00	de ✓ 108.99
15	3	L52148-33040 BRACKET, FR BUMPER	1.00	697.60	30.00	dis ✓ 488.32
16	4	L52021-33240 REINFORCEMENT	1.00	1400.20	30.00	? 980.14
17	5	L52146-33110 BRACKET, FR BUMPER	1.00	10.50	30.00	de ✓ 7.35
18	6	T53879-33030 RETAINER, FR FENDER	6.00	17.00	30.00	dis ✓ 1.40
19	7	T90189-06237 GROMMET, SCREW	2.00	2.60	30.00	rel ✓ 3.64
20	8	L52119-3T943 COVER, FR BUMPER	1.00	1601.80	30.00	fn ✓ 1121.26
21	9	L52542-33010 SEAL, FR BUMPER, CTR	1.00	128.10	30.00	cut ✓ 89.67
22	0	L53114-33050 GRILLE, RADIATOR,	1.00	278.60	30.00	cut ✓ 195.02
23	1	L52116-33100 SUPPORT, FR BUMPER LH	1.00	65.90	30.00	cut ✓ 46.13
24	2	L52115-33110 SUPPORT, FR BUMPER RH	1.00	65.90	30.00	dis ✓ 46.13
25	3	L53106-33010 GARNISH SUB-ASSY, LH	1.00	311.90	30.00	? 218.33
26	4	L53105-33010 GARNISH SUB-ASSY, RH	1.00	311.90	30.00	dis ✓ 218.33
27	5	L52128-33919 COVER, FR BUMPER LH	1.00	75.40	30.00	? 52.78
28	6	L52127-33905 COVER, FR BUMPER RH	1.00	75.40	30.00	dis ✓ 52.78
29	7	L52114-33520 BRACKET, FR BUMPER	1.00	223.70	30.00	? 156.59
30	8	L53101-33670 GRILLE SUB-ASSY,	1.00	2331.40	30.00	cut ✓ 1631.98
31	9	L53112-33510 GRILLE, RADIATOR,	1.00	312.80	30.00	cut ✓ 218.96
32	0	L88210-33120 SENSOR ASSY,	1.00	3235.40	30.00	? 2264.78
33	1	L53801-33230 FENDER SUB-ASSY, RH	1.00	2468.50	30.00	? 1727.95

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunoo Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Mr Neubronner Colin Michael
	Document No. 0	15 Leedon Heights #23-51 Singapore 266225
	Document Date 12/12/2024	Mobile: 84991057

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXZA10R	AEZGB S1	15/07/2019	SMN1360B	0	25583	SMN1360B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB11B1402010082	A25A5172534	60	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	2	L53807-33010 SHIELD SUB-ASSY, RH	1.00	731.30	30.00	511.91
35	3	T90467-07214 CLIP	10.00	3.80	30.00	26.60
36	4	L53295-33140 SEAL, COOL AIR	1.00	446.40	30.00	312.48
37	5	T53299-33020 PLATE, COOL AIR	1.00	36.20	30.00	25.34
38	6	T90467-07217 CLIP	12.00	3.60	30.00	30.24
39	7	L53141-33170 GARNISH, RADIATOR	1.00	1911.00	30.00	1337.70
40	8	L81145-33F21 UNIT, HEADLAMP RH	1.00	7119.60	30.00	4983.72
41	9	L89341-33220 C4 SENSOR, ULTRASONIC, chr	1.00	503.90	30.00	352.73
42	0	L85315-33520 JAR, WASHER, A	1.00	303.30	30.00	212.31
43	1	L85330-33070 MOTOR & PUMP ASSY,	1.00	404.90	30.00	283.43
44	2	L82114-33130 WIRE, ENGINE ROOM,	1.00	231.00	30.00	161.70
45	3	L52145-33110 BRACKET, FR BUMPER RH	1.00	10.50	30.00	7.35
46	4	L89341-33220 B4 SENSOR, ULTRASONIC, RH	1.00	630.40	30.00	441.28

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 24,676.39
	Please acknowledge receipt of vehicle	Parts 18,660.39 Labour 6,016.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 2,220.88
			Less 0.00
			Amount Due 26,897.27