

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vonn Siow Lie Mien

Date: 27 Dec 2024

Preliminary Advice

Insured Vehicle No	: QA1000L	Accident Date	: 11/12/2024
TP Vehicle No	: SLR3911P	Assignment Date	: 13/12/2024
Make	: TOYOTA C-HR HYBRID	Est. Duration of Repair	: 7
Date of Inspection	: 16/12/2024		
Inspection At	: L H EXPRESS MOTOR TRADING (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,289.80
Revised Amount	:S\$	18,589.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	18,589.48
Lump Sum Repair	:S\$	14,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.