



# Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED  
#42-0116 RAFFLES QUAY  
HONG LEONG BUILDING  
SINGAPORE 048581  
Registration No : SME2872G  
Chassis No : MRHFC5650JT001358  
Model : CIVIC 1.6 VTI YM2018  
Owner's Name : MOHAMED NOOR BIN ABDULLAH  
Ins Policy No. :  
Date of Accident :

Document No. : SQT24003303 Page 1  
Date : 12. Dec 2024  
Customer No. : WZF002  
Svc Advisor :  
Engine No : R16B25501588  
Date | Time : 12. Dec 2024 12:37:52 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

| Item            | Description                   | Qty | Unit Price | Disc % | Amount | 9% GST Amount | Amount incld GST |
|-----------------|-------------------------------|-----|------------|--------|--------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: ) |     |            |        |        |               |                  |
|                 | OWNER:                        |     |            |        |        |               |                  |
|                 | OWNER INSURER:                |     |            |        |        |               |                  |
|                 | ACC DATE:                     |     |            |        |        |               |                  |
|                 | SURVEYED BY:                  |     |            |        |        |               |                  |
|                 | DATE:                         |     |            |        |        |               |                  |
|                 | REF NO:                       |     |            |        |        |               |                  |
|                 | TP INSURER:                   |     |            |        |        |               |                  |
|                 | TP VEH:                       |     |            |        |        |               |                  |
| 84521-TEA-Q01ZA | LID ASSYSAPARE TIRE           | 1   | X 72.80    | 25     | 54.60  | 4.91          | 59.51            |
| 84601-TEA-Q01ZA | LINING ASSYR.TRUNK SIDE       | 1   | X 59.10    | 25     | 44.32  | 3.99          | 48.31            |
| 84651-TEA-Q01ZA | LINING ASSY,L.TRUNK SIDE      | 1   | X 59.10    | 25     | 44.32  | 3.99          | 48.31            |
| 34150-TEX-Y01   | LIGHT ASSYR.LID               | 1   | X 148.00   | 25     | 111.00 | 9.99          | 120.99           |
| 34155-TEX-Y01   | LIGHT ASSYL.LID               | 1   | X 148.00   | 25     | 111.00 | 9.99          | 120.99           |
| 33500-TEA-T01   | TAILLIGHT ASSY,R.             | 1   | X 316.50   | 25     | 237.37 | 21.36         | 258.73           |
| 33550-TEA-T01   | TAILLIGHT ASSYL.              | 1   | X 340.50   | 25     | 255.37 | 22.98         | 278.35           |
| 32131-TEA-R00   | SUB CORDRR.BUMPER CORNER SENS | 1   | X 34.00    | 25     | 25.50  | 2.30          | 27.80            |
| 39680-TEX-Y41ZT | SENSOR ASSY,PARKING T99       | 4   | X 174.40   | 25     | 523.20 | 47.09         | 570.29           |
| 39670-TEX-Y01   | SENSOR UNITPARKING            | 1   | X 75.70    | 25     | 56.77  | 5.11          | 61.88            |
| 65550-TEA-T00ZZ | PAN COMPSPARE TIRE            | 1   | X 262.20   | 25     | 196.65 | 17.70         | 214.35           |
| 04636-TEA-T00ZZ | PANEL SETR.RR.OUTSIDE         | 1   | X 861.40   | 25     | 646.05 | 58.14         | 704.19           |
| 71101-TEA-T00ZZ | FACEFR.BUMPER                 | 1   | de 579.90  | 25     | 434.92 | 39.14         | 474.06           |
| 71103-TEA-T00   | GARNISHR.FR.BUMPER SIDE       | 1   | X 21.80    | 25     | 16.35  | 1.47          | 17.82            |
| 71108-TEA-T00   | GARNISHL.FR.BUMPER SIDE       | 1   | X 21.80    | 25     | 16.35  | 1.47          | 17.82            |
| 71130-TEA-T00   | BEAM COMPFR.BUMPER            | 1   | 16 418.60  | 25     | 313.95 | 28.26         | 342.21           |
| 71140-TEA-T00   | BEAMR.FR.BUMPER UPPER         | 1   | 14 91.40   | 25     | 68.55  | 6.17          | 74.72            |
| 71150-TEA-T00   | BEAM COMPFR.BUMPER CENTER UP  | 1   | X 260.00   | 25     | 195.00 | 17.55         | 212.55           |
| 71190-TEA-T00   | BEAML.FR.BUMPER UPPER         | 1   | 14 91.40   | 25     | 68.55  | 6.17          | 74.72            |

Printed on 12/12/2024 1:20:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



# QUOTATION

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED  
#42-0116 RAFFLES QUAY  
HONG LEONG BUILDING  
SINGAPORE 048581  
Registration No : SME2872G  
Chassis No : MRHFC5650JT001358  
Model : CIVIC 1.6 VTI YM2018  
Owner's Name : MOHAMED NOOR BIN ABDULLAH  
Ins Policy No. :  
Date of Accident :

Document No. : SQT24003303 Page 2  
Date : 12. Dec 2024  
Customer No. : WZF002  
Svc Advisor :  
Engine No : R16B25501588  
Date | Time : 12. Dec 2024 12:37:52 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

| Item            | Description                                        | Qty           | Unit Price                       | Disc % | Amount         | 9% GST Amount | Amount incld GST |
|-----------------|----------------------------------------------------|---------------|----------------------------------|--------|----------------|---------------|------------------|
| 71193-TEA-T01   | SPACERR.FR.BUMPER SIDE                             | 1 <i>net</i>  | 10.40 /                          | 25     | 7.80           | 0.70          | 8.50             |
| 71198-TEA-T01   | SPACERL.FR.BUMPER SIDE                             | 1 <i>net</i>  | 10.40 /                          | 25     | 7.80           | 0.70          | 8.50             |
| 91505-TM8-003   | CLIP,BUMPER                                        | 16 <i>net</i> | 2.30 /                           | 25     | 27.60          | 2.48          | 30.08            |
| 71121-TEA-T02   | BASE,FR.GRILLE CHROME                              | 1 <i>cm</i>   | 89.20 /                          | 25     | 66.90          | 6.02          | 72.92            |
| 71125-TEA-T01   | MOLDINGFR.GRILLE                                   | 1 <i>cm</i>   | 121.40 /                         | 25     | 91.05          | 8.19          | 99.24            |
| 75700-TBA-A00   | EMBLEM                                             | 1 <i>net</i>  | 18.20 /                          | 25     | 13.65          | 1.23          | 14.88            |
| 90301-ST0-003   | NUT,PUSH 3MM                                       | 2 <i>net</i>  | 2.10 /                           | 25     | 3.15           | 0.28          | 3.43             |
| 33100-TEC-Q01   | HEADLIGHT ASSY,R.                                  | 1 <i>cr</i>   | 708.80 /                         | 25     | 531.60         | 47.84         | 579.44           |
| 33150-TEC-Q01   | HEADLIGHT ASSYL.                                   | 1 <i>cr</i>   | 708.80 /                         | 25     | 531.60         | 47.84         | 579.44           |
| BO-NUM-COMP-L   | NUMBER PLATE WITH CASING-L(N)                      | 1 <i>bt</i>   | 45.00 /                          |        | 45.00          | 4.05          | 49.05            |
| 60211-TBA-A00ZZ | PANELR.FENDER                                      | 1             | x 450.80                         | 25     | 338.10         | 30.43         | 368.53           |
| 60261-TBA-A00ZZ | PANELL.FENDER                                      | 1             | x 450.80                         | 25     | 338.10         | 30.43         | 368.53           |
| 60100-TEA-T00ZZ | HOOD COMPENGINE                                    | 1             | x 724.70                         | 25     | 543.52         | 48.92         | 592.44           |
| 71410-TEA-T01   | BULKHEAD ASSY,FR. - photo.                         | 1             | X 1426.60                        | 25     | 1069.95        | 96.30         | 1166.25          |
| 80100-TBA-A01   | CONDENSER ASSY                                     | 1 <i>bt</i>   | 704.40 /                         | 25     | 528.30         | 47.55         | 575.85           |
| 19010-5FA-Z01   | RADIATOR COMP                                      | 1 <i>cr</i>   | 1100.50                          | 25     | 825.37         | 74.28         | 899.65           |
| Sum Item        |                                                    |               |                                  |        | <u>8389.31</u> | <u>755.02</u> | <u>9,144.33</u>  |
| BOSUN           | SUNDRIES                                           | 1             | 110.00 <i>50</i>                 |        | 110.00         | 9.90          | 119.90           |
| BML01I          | INSPECT FR LIGHTING MECHANISMS & FOCUS             | 1             | 250.00 <i>220</i>                |        | 250.00         | 22.50         | 272.50           |
| BMA01D          | REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.      | 1             | 580.00 ✓                         |        | 580.00         | 52.20         | 632.20           |
| BMC01D          | REMOVE & INSTALL RADIATOR WITH FITTINGS.           | 1             | 530.00 ✓                         |        | 530.00         | 47.70         | 577.70           |
| BKBH01S         | STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.     | 1             | 4000.00 <i>1950 + 1 bulkhead</i> |        | 4000.00        | 360.00        | 4360.00          |
| BP03R           | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) | 1             | 3200.00 <i>1560</i>              |        | 3200.00        | 288.00        | 3488.00          |
| BOJSE           | SEALANT FOR REAR END PANEL                         | 1             | 120.00 <i>110</i>                |        | 120.00         | 10.80         | 130.80           |
| BOJSE           | SEALANT FOR REAR FLOOR PANEL                       | 1             | 120.00 <i>X</i>                  |        | 120.00         | 10.80         | 130.80           |
| BOJSE           | SEALANT FOR TRUNK                                  | 1             | 120.00 <i>X</i>                  |        | 120.00         | 10.80         | 130.80           |

Printed on 12/12/2024 1:20:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



# Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg. No. : M200050223  
Company Ref. No. : S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED  
#42-0116 RAFFLES QUAY  
HONG LEONG BUILDING  
SINGAPORE 048581  
Registration No : SME2872G  
Chassis No : MRHFC5650JT001358  
Model : CIVIC 1.6 VTI YM2018  
Owner's Name : MOHAMED NOOR BIN ABDULLAH  
Ins Policy No. :  
Date of Accident :

Document No. : SQT24003303 Page 3  
Date : 12. Dec 2024  
Customer No. : WZF002  
Svc Advisor :  
Engine No : R16B25501588  
Date | Time : 12. Dec 2024 12:37:52 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

| Item      | Description                                        | Qty | Unit Price | Disc %    | Amount   | 9% GST Amount | Amount incld GST |
|-----------|----------------------------------------------------|-----|------------|-----------|----------|---------------|------------------|
| BML02I    | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER      | 1   | 250.00     | 220 /     | 250.00   | 22.50         | 272.50           |
| BA02R     | REMOVE & RENEW REVERSE SENSORS-4 PCS (N)           | 1   | 250.00     | 220 /     | 250.00   | 22.50         | 272.50           |
| BC012R    | RESET VEHICLE SMART ENTRY SYSTEM                   | 1   | 650.00     | 580 /     | 650.00   | 58.50         | 708.50           |
| BC011R    | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA        | 1   | 650.00     | 580 /     | 650.00   | 58.50         | 708.50           |
| BMI03D    | REMOVE & INSTALL REAR COMPARTMENT LININGS          | 1   | 650.00     | ✓ /       | 650.00   | 58.50         | 708.50           |
| BKRP02M   | CUT OFF & RENEW RR PANEL. STRAIGHTEN               | 1   | 6000.00    | 2600 /    | 6000.00  | 540.00        | 6540.00          |
| BP05R     | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) | 1   | 3200.00    | 3120 /    | 3200.00  | 288.00        | 3488.00          |
| BMI02D    | REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK      | 1   | 650.00     | X nn      | 650.00   | 58.50         | 708.50           |
| BMF00D    | RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)         | 1   | 650.00     | X nn      | 650.00   | 58.50         | 708.50           |
| BOSUN     | REMOVE AND RE-INSTALL TRUNK SPOILER                | 1   | 580.00     | 420. X nn | 580.00   | 52.20         | 632.20           |
| BOBC      | BODY UNDERSIDE COATING (N)                         | 1   | 580.00     | 480 /     | 580.00   | 52.20         | 632.20           |
| BKOT00R   | REMOVE & RENEW RR FLOOR INSULATOR.(N)              | 1   | 480.00     | X nn      | 480.00   | 43.20         | 523.20           |
| Sum Labor |                                                    |     |            |           | 23620.00 | 2,125.80      | 25,745.80        |

Survey By : Taufik 97495749  
Date & Time : 12/12/24 @ 3:15 pm  
Excess : WP' 12 days  
Status : 1/1p Resurvey before paint  
Signature : Taufik e/khanda.com

Total Amount 32,009.31 2,880.82 34,890.13  
Total (Inclusive of GST) 34,890.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed on 12/12/2024 1:20:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.