

ASS. REC. BY: Tauhin

REF: CS/FC/24/20/94/Tn43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: \$66K

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seer _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Sin Hai Vehicle: IN / OUT

Veh No: SME 28726 Yr Regn: 2018, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Civic 1.6 cc 1597

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 97597 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC 5650 JTOO 1358

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 Rear: 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 16/12/24

Survey held at Kah Muter Alexander

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / I.E.I. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : _____

Survey Fee: _____

Transportation: _____

\$ + RS. SI

Photos

Others



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SME2872G
Chassis No : MRHFC5650JT001358
Model : CIVIC 1.6 VTI YM2018
Owner's Name : MOHAMED NOOR BIN ABDULLAH
Ins Policy No. :
Date of Accident :

Document No. : SQT24003303 Page 1
Date : 12. Dec 2024
Customer No. : WZF002
Svc Advisor :
Engine No : R16B25501588
Date | Time : 12. Dec 2024 12:37:52 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
84521-TEA-Q01ZA	LID ASSYSAPARE TIRE	1	X 72.80	25	54.60	4.91	59.51
84601-TEA-Q01ZA	LINING ASSYR.TRUNK SIDE	1	X 59.10	25	44.32	3.99	48.31
84651-TEA-Q01ZA	LINING ASSY,L.TRUNK SIDE	1	X 59.10	25	44.32	3.99	48.31
34150-TEX-Y01	LIGHT ASSYR.LID	1	X 148.00	25	111.00	9.99	120.99
34155-TEX-Y01	LIGHT ASSYL.LID	1	X 148.00	25	111.00	9.99	120.99
33500-TEA-T01	TAILLIGHT ASSY,R.	1	X 316.50	25	237.37	21.36	258.73
33550-TEA-T01	TAILLIGHT ASSYL.	1	X 340.50	25	255.37	22.98	278.35
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	? 34.00	25	25.50	2.30	27.80
39680-TEX-Y41ZT	SENSOR ASSY,PARKING T99	4	? 174.40	25	523.20	47.09	570.29
39670-TEX-Y01	SENSOR UNITPARKING	1	? 75.70	25	56.77	5.11	61.88
65550-TEA-T00ZZ	PAN COMPSPARE TIRE	1	? 262.20	25	196.65	17.70	214.35
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE	1	? 861.40	25	646.05	58.14	704.19
71101-TEA-T00ZZ	FACEFR.BUMPER	1	de 579.90	25	434.92	39.14	474.06
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	? 21.80	25	16.35	1.47	17.82
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE	1	? 21.80	25	16.35	1.47	17.82
71130-TEA-T00	BEAM COMPFR.BUMPER	1	? 418.60	25	313.95	28.26	342.21
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	? 91.40	25	68.55	6.17	74.72
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UP	1	? 260.00	25	195.00	17.55	212.55
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	? 91.40	25	68.55	6.17	74.72

Printed on 12/12/2024 1:20:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



QUOTATION

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg. No. : M200050223
Company Ref. No. : S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SQT24003303	Page	2
	#42-0116 RAFFLES QUAY	Date	: 12. Dec 2024		
	HONG LEONG BUILDING	Customer No.	: WZF002		
	SINGAPORE 048581	Svc Advisor	:		
Registration No	: SME2872G	Engine No	: R16B25501588		
Chassis No	: MRHFC5650JT001358	Date Time	: 12. Dec 2024 12:37:52 PM		
Model	: CIVIC 1.6 VTI YM2018	Surveyor Name	:		
Owner's Name	: MOHAMED NOOR BIN ABDULLAH	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1 <i>net</i>	10.40	25	7.80	0.70	8.50
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1 <i>net</i>	10.40	25	7.80	0.70	8.50
91505-TM8-003	CLIP,BUMPER	16 <i>net</i>	2.30	25	27.60	2.48	30.08
71121-TEA-T02	BASE,FR.GRILLE CHROME	1 <i>cur</i>	89.20	25	66.90	6.02	72.92
71125-TEA-T01	MOLDINGFR.GRILLE	1 <i>cur</i>	121.40	25	91.05	8.19	99.24
75700-TBA-A00	EMBLEM	1 <i>net</i>	18.20	25	13.65	1.23	14.88
90301-ST0-003	NUT,PUSH 3MM	2 <i>net</i>	2.10	25	3.15	0.28	3.43
33100-TEC-Q01	HEADLIGHT ASSY,R.	1 ?	708.80	25	531.60	47.84	579.44
33150-TEC-Q01	HEADLIGHT ASSYL.	1 ?	708.80	25	531.60	47.84	579.44
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1 <i>bt</i>	45.00		45.00	4.05	49.05
60211-TBA-A00ZZ	PANELR.FENDER	1 x	450.80	25	338.10	30.43	368.53
60261-TBA-A00ZZ	PANELL.FENDER	1 x	450.80	25	338.10	30.43	368.53
60100-TEA-T00ZZ	HOOD COMPENGINE	1 x	724.70	25	543.52	48.92	592.44
71410-TEA-T01	BULKHEAD ASSY,FR. - <i>photo</i>	1 ?	1426.60	25	1069.95	96.30	1166.25
80100-TBA-A01	CONDENSER ASSY	1 <i>bt</i>	704.40	25	528.30	47.55	575.85
19010-5FA-Z01	RADIATOR COMP	1 ?	1100.50	25	825.37	74.28	899.65
Sum Item					<u>8389.31</u>	<u>755.02</u>	<u>9,144.33</u>
BOSUN	SUNDRIES	1	110.00 <i>50</i>		110.00	9.90	119.90
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	250.00 <i>220</i>		250.00	22.50	272.50
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	580.00 ✓		580.00	52.20	632.20
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	530.00 ✓		530.00	47.70	577.70
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	4000.00 <i>1950 + 1 bulkhead</i>		4000.00	360.00	4360.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	3200.00 <i>1560</i>		3200.00	288.00	3488.00
BOJSE	SEALANT FOR REAR END PANEL	1	120.00 <i>MC</i>		120.00	10.80	130.80
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	120.00 X		120.00	10.80	130.80
BOJSE	SEALANT FOR TRUNK	1	120.00 X		120.00	10.80	130.80

Printed on 12/12/2024 1:20:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SME2872G
Chassis No : MRHFC5650JT001358
Model : CIVIC 1.6 VTI YM2018
Owner's Name : MOHAMED NOOR BIN ABDULLAH
Ins Policy No. :
Date of Accident :

Document No. : SQT24003303 Page 3
Date : 12. Dec 2024
Customer No. : WZF002
Svc Advisor :
Engine No : R16B25501588
Date | Time : 12. Dec 2024 12:37:52 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00	220	250.00	22.50	272.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00	220	250.00	22.50	272.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	580	650.00	58.50	708.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	580	650.00	58.50	708.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	✓	650.00	58.50	708.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	6000.00	2600	6000.00	540.00	6540.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3200.00	3120	3200.00	288.00	3488.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00	X	650.00	58.50	708.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	X	650.00	58.50	708.50
BOSUN	REMOVE AND RE-INSTALL TRUNK SPOILER	1	580.00	420.?	580.00	52.20	632.20
BOBC	BODY UNDERSIDE COATING (N)	1	580.00	480	580.00	52.20	632.20
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	480.00	X	480.00	43.20	523.20
Sum Labor					23620.00	2,125.80	25,745.80

Survey By

Date & Time

Excess

Status

Signature

Taufik 97495749
12/12/24 @ 3:15pm 12 days
WP'
1/1p Resurvey before paint
Taufik e/khanda.com

Total Amount 32,009.31 2,880.82 34,890.13

Total (Inclusive of GST) 34,890.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed on 12/12/2024 1:20:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.