



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24070017/Aqh3
50 RAFFLES PLACE #03-03	Date:	05/09/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6849Z	Veh. Inspected	SHC 8566X
Policy No.	-	Coverage	0
Claim No.	CMTD2402150/RUC	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	01/07/2024

2. Vehicle Details

Make & Model	HYUNDAI IONIQ	C.C	1580
Engine No.	G4LEKU422252	Year of Reg.	28/07/2021
Chassis No.	KMHC851CVLU193172	Colour	BLUE
Odometer	471871 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	WEST LAKE	6
L/H Front Tyre	195/65 R15	WEST LAKE	6
R/H Rear Tyre	195/65 R15	WEST LAKE	6
L/H Rear Tyre	195/65 R15	WEST LAKE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/06/2024	Inspection Date	01/07/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days