

ASSIGNMENT

Front: _____ Date: _____
 Est: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To In _____ Vehicle No: _____
 at V/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: Tlveh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC8566X Yr Regn: 2021, July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tonig C.O. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 471871 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C851CVLU193172

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
 R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 01/07/24

Survey held at

Carport Kojing

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Smpo

COE Expiry

Estimate given during : Yes C
 1st Survey : No C

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
 Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos
 Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Report Format: _____

Report Form: _____

CONFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8566X
MAKE REG. 28.07.2021
MODEL IONIQ G3

- K Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during 29.06.2024
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed

CHIANG/SOMPO

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET RH/LH		\$55.80
10	REAR BUMPER CLIPS		\$2.20
1	REAR BUMPER REINFORCEMENT		\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH		\$138.10
1	BOOTLID COVER		\$2,549.70
1	BOOTLID LOCK UPPER		\$224.00
1	BOOTLID H EMBLEM		\$28.00
1	BOOTLID HYBRID		\$24.30
1	BOOTLID LONIQ		\$31.30
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER LOWER MOULDING		\$155.00
1	REAR END PANEL		\$532.00
1	REAR PANEL LOWER PANEL		\$208.90
1	REAR BUMPER FOG LAMP		\$201.50
2	NUMBER PLATE LAMP LH/RH		\$85.30
1	ANTENNA ASSY -SMART		\$40.50
SUB TOTAL			\$5,881.05
25.00%			\$1,470.26
DISCOUNTED TOTAL			\$4,410.78
2	WSCREEN SEALANT		\$23.00
1	REAR BUMPER MAT		\$46.00
1	REAR NUMBER PLATE/W HOLDER		\$50.00
1	REAR REVERSE SENSOR		\$55.00
1	BOOTLID APP LOGO STCKER		\$180.00
2	BOOTLID COMFORT LOGO/TEL NO. STICKER		\$40.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$60.00
1	BOOTLID ADVERTISEMENT		\$200.00
			\$100.00
			\$731.00
Labour Charge			
Panel Beating			\$1,200.00
Spray Painting Charge			\$700.00
Check wiring			\$60.00
Tuff Kote			\$90.00
Remove/Refix Rear windscreen UPPER /LOWER			\$180.00
Remove/refix Reverse sensor			\$60.00
TOTAL LABOUR			\$2,290.00
ESTIMATE TOTAL			\$7,431.78
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

adrianling
@klkauto.com

Adrian G
1/8 01/07/24.

03 Days

At 30pm

380
380
30
50