

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

**D.O.A :** 06/12/2024**OWNER :****REG. NO. :** SLR3880U**MAKE/MODEL :** TOYOTA VIOS**ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE**

| <u>QTY</u> | <u>DESCRIPTION</u>              | <u>AMOUNT(\$)</u> |
|------------|---------------------------------|-------------------|
|            | <u>LIST ITEMS</u>               |                   |
| 1          | Rear Bootlid                    | \$ 985.70         |
| 2          | Rear Boot Hinges                | \$ 171.40         |
| 1          | Rear Boot Inner Trim            | \$ 188.50         |
| 2          | Rear Boot Lamps                 | \$ 868.90         |
| 1          | Rear Boot Lock                  | \$ 145.00         |
| 1          | Rear Boot Lock Catch            | \$ 60.30          |
| 1          | Rear Boot Logo                  | \$ 89.70          |
| 1          | Rear Boot Rubber                | \$ 145.70         |
| 1          | Rear Boot "toyota" Emblem       | \$ 80.30          |
| 1          | Rear Boot "vios" Emblem         | \$ 75.70          |
| 1          | Rear Boot Outer Chrome Moulding | \$ 288.50         |
| 2          | Rear Taillamp                   | \$ 1,230.00       |
| 1          | Rear End Panel                  | \$ 777.40         |
| 1          | Rear End Panel Inner Garnish    | \$ 200.30         |
| 1          | Rear Keyless Sensor             | \$ 185.20         |
| 1          | Rear Bumper                     | \$ 879.60         |
| 2          | Rear Bumper Top Brackets        | \$ 181.80         |
| 2          | Rear Bumper Side Brackets       | \$ 97.00          |
| 2          | Rear Bumper Reflectors          | \$ 120.20         |
| 1          | Rear Bumper Reinforcement       | \$ 415.00         |
| 2          | Rear Bumper Reinforcement Stays | \$ 161.00         |
| 2          | Rear Bumper Side Retainers      | \$ 130.00         |
|            |                                 |                   |
|            |                                 | \$ 7,477.20       |
|            | LESS 25%                        | \$ 1,869.30       |
|            |                                 | \$ 5,607.90       |

SPECIAL NETT ITEMS

|   |                               |       |        |
|---|-------------------------------|-------|--------|
| 1 | Rear Bumper Clip (1 Set)      | \$    | 50.00  |
| 1 | Rear Number Plate with Holder | \$    | 50.00  |
| 1 | Rear Reverse Sensor (1 Set)   | \$    | 350.00 |
|   |                               | <hr/> |        |
|   |                               | \$    | 450.00 |

S/N

LABOUR CHARGES

|   |                                                       |       |          |
|---|-------------------------------------------------------|-------|----------|
| 1 | To remove, replace damaged lamps & check up wiring    | \$    | 80.00    |
| 2 | To remove & refit inner garnishes                     | \$    | 180.00   |
| 3 | To remove & refit rear reverse sensor                 | \$    | 180.00   |
| 4 | To transfer rear tailgate mechanism & wiring assembly | \$    | 80.00    |
| 5 | To apply undercoating                                 | \$    | 200.00   |
| 6 | Panel Beating                                         | \$    | 1,500.00 |
| 7 | To re-spray the affected areas                        | \$    | 1,400.00 |
|   |                                                       | <hr/> |          |
|   |                                                       | \$    | 3,620.00 |

|  |  |       |          |
|--|--|-------|----------|
|  |  | <hr/> |          |
|  |  | \$    | 9,677.90 |
|  |  | <hr/> |          |