

ESTIMATE OF REPAIR

Veh# : SGS6095D

Model:

HONDA VEZEL

Accident Date : 11/12/2024

Location : WOODLAND CHECKPOINT PICK UP

3P:

SHB555EH (1ST CAP)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1PC	Front headlamp R <i>RR</i>	2,180.00	1784	
2	2 pcs	Front headlamp lower bracket R <i>X</i>	76.00		
3	1PC	Front headlamp side bracket R <i>X</i>	70.00		
4	1PC	Front bumper <i>RR</i>	801.70		
5	2 pcs	Front bumper side retainer R/L (RH) <i>RR</i>	41.20		
6	1 set	Front bumper clip <i>RR</i>		50.00	37
7	1PC	Front bumper lower lid <i>X</i>	381.00		
8	1PC	Front bumper foglamp RH <i>X</i>	327.70		
9	1PC	Front bumper foglamp cover RH <i>CUT</i>	50.00		
		Wheel arch gnrish RH <i>\$145</i> <i>RR \$201</i>	Sub Total:	3,927.60	50.00
				20%	0%
		After Less %:	3,142.08	50.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign accident affected area.	500.00	200	
2		To spray paint on affected area.	400.00	300	
3		To check wiring	80.00	30	
4		To rust proof affected area.	120.00	X	
		Sub Total:	1,100.00		
		Total:	4,292.08		

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

SGS6095D ESTIMATEPg1