

ASS. REC. BY:

REF:

1001

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

06/29

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBD 917K

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C.

2982

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

245373

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTPA 735 YX. OK 203047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195R15X8

R:

155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7 7

mm

L/Bal.

6

mm

L/Bal.

7 7

mm

D.O.A.

10/12/24

D.O.I.

13/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S + RS. SI

) Photos

) Others

Report Format :

ump Sum / I.B.I: (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

Not Withheld
L1 Rmp &
Primary After Pain
6 days

DATE : 12-12-2024
 VEHICLE : GBD 917 K
 MAKE/MODEL : TOYOTA DYNA
 CHASSIS NO : JTFAT35YXOK203047
 MILEAGE :
 TYRE SIZE : FRT 195 R 15 C REAR 155 R 12 C
 DOA : 10-12-2024
 TP INSURANCE : INCOME

List items

01 PC	FRONT BUMPER		Bus	950.16	✓
01 PC	FRONT REINFORCEMENT		\$ R	470.21	X
01 PC	FRONT GRILLE PROTECTOR		\$ Sn	51.75	X
01 PC	FRONT GRILLE		\$	755.12	7
01 PC	FRONT GRILLE MOULDING		\$ Rn	55.80	✓
01 PC	FRONT TOP PANEL		\$ R	1,534.96	X
01 PC	FRONT TOP PANEL GARNISH		\$ Rn	483.76	X
01 PC	FRONT EMBLEM (LOGO)		\$	115.08	7
01 PC	FRONT EMBLEM (DYNA)		\$ Rn	117.76	✓
01 PC	FRONT HEAD LAMP (L)		\$	1,231.47	7
01 PC	FRONT HEAD LAMP (R)		\$	1,231.47	7
01 PC	FRONT HEAD LAMP PROTECTOR (L)		\$ Rn	44.20	X
01 PC	FRONT HEAD LAMP PROTECTOR (R)		\$ Rn	44.20	X
01 PC	FRONT DOOR (L)			REPAIR	
01 PC	FRONT DOOR (R)			REPAIR	
01 PC	REAR BODY TAIL GATE		Rn \$	1,391.91	✓
01 PC	REAR BODY TAIL GATE CHAIN (L)		\$ R	95.84	X
01 PC	REAR BODY TAIL GATE CHAIN (R)		\$ R	95.84	X
04 PCS	REAR BODY TAIL GATE HINGES	@\$94.44	\$ R	377.76	X
01 PC	REAR BODY TAIL GATE LOCK (L)		\$ R	183.40	✓
01 PC	REAR BODY TAIL GATE LOCK (R)		\$ R	183.40	X
01 PC	REAR BODY FLOOR PANEL			REPAIR	
01 PC	REAR TAIL LAMP (L)		\$	232.12	7
01 PC	REAR TAIL LAMP COVER/HOLDER (L)		\$ Rn	183.24	✓
01 PC	REAR TAIL GATE PANEL STICKER 'TOYOTA'		Rn	269.80	✓

251

\$ 10,099.25

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett Item:

10 PCS	FRONT GRILLE CLIP	@\$8.00	\$ 80.00	✓
10 PCS	FRONT TOP PANEL CLIP	@\$8.00	\$ 80.00	X
01 PC	'5 PAX' STICKER		\$ 30.00	150n
01 PC	'70 KM' STICKER		\$ 30.00	150n
01 PC	FRONT NUMBER PLATE		\$ 30.00	250n
01 PC	TAIL GATE ALUMINIUM PANEL		\$ 500.00	X
01 PC	REAR STEP BRACKET		\$ 450.00	150n
01 PC	REVERSE SENSOR		\$ 280.00	200n
			<u>\$ 1,480.00</u>	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,500.00	800
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 1,500.00	900
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$ 200.00	300
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$ 150.00	400
		<u>\$ 3,350.00</u>

TOTAL PARTS	\$ 10,099.25
SPECIAL NETT ITEM	\$ 1,480.00
TOTAL LABOUR	\$ 3,350.00
TOTAL COST OF REPAIR	<u>\$ 14,929.25</u>