



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24120201/Kqh3e2
75 BRAS BASAH ROAD	Date:	23/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNK 866U	Veh. Inspected	GBD 917K
Policy No.	-	Coverage	0
Claim No.	MT/1307931-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	12/12/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2982
Engine No.	1KD2400579	Year of Reg.	04/06/2014
Chassis No.	JTFAT35YX0K203047	Colour	SILVER
Odometer	245373 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15X8	YOKOHAMA	6
L/H Front Tyre	195 R15X8	YOKOHAMA	6
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	7/7
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	7/7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/12/2024	Inspection Date	13/12/2024 (12:00)
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days