

Date: 11-12-2024  
Vehicle No: SMS8865P  
Model: Hyundai I30  
Chassis: TMAH3513VLJ114930  
Reg.Year: 12.9.2019

*Not Authorized*  
*11 Sep @ 4300h*  
*Recovery After Pain*  
*3day*

Third Party Insurer: Auto & General  
Third Party Veh No: SMS5988M  
Date of Accident: 10/12/2024  
Estimator: Loong  
Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                          | QTY | UNIT S\$ | AMOUNT S\$       |
|-------------|--------------------------------------|-----|----------|------------------|
| 1           | REAR BUMPER                          | 1   |          | Bu \$1,300.00    |
| 2           | REAR LH BUMPER RETAINER              | 1   |          | Rn \$90.00       |
| 3           | REAR RH BUMPER RETAINER              | 1   |          | In \$90.00       |
| 4           | REAR BUMPER LOWER                    | 1   |          | na 1DIT \$390.00 |
| 5           | REAR LH LICENCE PLATE LAMP           | 1   |          | cm \$70.00       |
| 6           | REAR RH LICENCE PLATE LAMP           | 1   |          | cm \$70.00       |
| 7           | REAR BUMPER REINFORCEMENT            | 1   |          | Bu \$700.00      |
| 8           | REAR LH BUMPER REINFORCEMENT BRACKET | 1   |          | R \$390.00       |
| 9           | REAR RH BUMPER REINFORCEMENT BRACKET | 1   |          | R \$390.00       |
| 10          | REAR REVERSE SENSOR                  | 2   | \$190.00 | Sm \$380.00      |
| 11          | SMART KEY ANTENNA                    | 1   |          | cm \$50.00       |
| 12          | REAR BUMPER TOWING COVER             | 1   |          | Re \$50.00       |
| 13          | REAR BOOT HYUNDAI LOGO               | 1   |          | nn \$70.00       |
| 14          | REAR BOOT I30 EMBLEM                 | 1   |          | nn \$50.00       |
| 15          | REAR BOOT 1.4T EMBLEM                | 1   |          | nn \$60.00       |
| 16          | REAR EXHAUST TAIL PIPE               | 1   |          | Bt \$3,200.00    |
| 17          | REAR END PANEL                       | 1   |          | REPAIR           |
| 18          | REAR BOOT                            | 1   |          | REPAIR           |
| SUB TOTAL   |                                      |     |          | \$7,350.00       |
| LESS 20%    |                                      |     |          | -\$1,470.00      |
| PARTS TOTAL |                                      |     |          | \$5,880.00       |

| NO.       | SPECIAL NETT                             | QTY | UNIT S\$ | AMOUNT S\$  |
|-----------|------------------------------------------|-----|----------|-------------|
| 1         | REAR BUMPER CLIPS                        | 1   |          | na \$55.00  |
| 2         | REAR BUMPER LOWER CLIPS                  | 1   |          | na \$50.00  |
| 3         | REAR LICENCE PLATE NUMBER WITH FRAME     | 1   |          | na \$55.00  |
| 4         | REAR REVERSE SENSOR MOUNTING BRACKET SET | 1   |          | na \$180.00 |
| S/N TOTAL |                                          |     |          | \$340.00    |

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$900.00 400h

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$800.00 400h

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 11-12-2024  
Vehicle No: SMS8865P  
Model: Hyundai I30  
Chassis: TMAH3513VLJ114930  
Reg.Year: 12.9.2019

Third Party Insurer: Auto & General  
Third Party Veh No: SMS5988M  
Date of Accident: 10/12/2024  
Estimator: Loong  
Surveyor:

|                                                                                                                                     |               |
|-------------------------------------------------------------------------------------------------------------------------------------|---------------|
| TO REMOVE AND REFIT REAR EXHAUST TAIL PIPE TO ENABLE BODYWORK REPAIR                                                                | in \$150.00 X |
| TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS, LININGS, GARNISH, COVER AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR | \$250.00 801  |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.                                                                | \$100.00 501  |
| TO CHECK WIRING & ELECTRICAL SYSTEM.                                                                                                | \$100.00 151  |

LABOUR TOTAL \$2,300.00

TOTAL \$8,520.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 26-12-2024  
Vehicle No: SMS8865P  
Model: Hyundai I30  
Chassis: TMAH3513VLJ114930  
Reg.Year: 12.9.2019

Third Party Insurer: Auto & General  
Third Party Veh No: SMS5988M  
Date of Accident: 10/12/2024  
Estimator: Loong  
Surveyor:

## SUPPLEMENTARY ESTIMATE

| NO.         | DESCRIPTION                            | QTY | UNIT S\$ | AMOUNT S\$ |
|-------------|----------------------------------------|-----|----------|------------|
| 1           | REAR BUMPER WIRE HARNESS <i>482.60</i> | 1   |          | \$620.00   |
| SUB TOTAL   |                                        |     |          | \$620.00   |
| LESS 20%    |                                        |     |          | -\$124.00  |
| PARTS TOTAL |                                        |     |          | \$496.00   |