

CL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 20100228E

VEHICLE INSPECTION REPORT

To: Redgold Car Rental Pte Ltd
C/o: Trident Auto Service Centre Pte Ltd
8 Kaki Bukit Ave 4
#02-42 Premier @ Kaki Bukit, Singapore 415875

Date : 25 April 2023
Our ref : TRI/04/2301/TP

Accident Date : 23 March 2023
Inspection Date : 20 April 2023
Repairer Name : Trident Auto Service Centre Pte Ltd
8 Kaki Bukit Ave 4
#02-42 Premier @ Kaki Bukit, Singapore 415875

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: SMG 2554 P	Year / Capacity	: 2018 / 1797 cc
Make / Model	: Toyota Noah Hybrid	Colour	: Grey
Chassis No	: ZWR800344687	Mileage	: 343102
Engine No	: 2ZR0C35168		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Triangle	195/65 R15	5 mm	Sport
Front Offside	: Triangle	195/65 R15	5 mm	Sport
Rear Nearside	: Triangle	195/65 R15	5 mm	Sport
Rear Offside	: Triangle	195/65 R15	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 31 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$4,200.00 on a contractual basis.

Under normal circumstances, the repair period would be about 4 (Four) working days.

SCL APPRAISER PTE LTD

Vehicle Registration No.: SMG 2554 P

Our Ref No.:

TRI/04/2301/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear n/s fender	Repair	\$ 200.54					
1	N/s rocker panel side skirt	Damage	\$ 700.12	\$	700.12			Ry
1	N/s sliding door	Damage	\$ 1,800.17	\$	1,800.17			Ry 1594.70
1	N/s sliding door rubber	Necessary	\$ 200.53	\$	200.53			X
			\$ 2,901.36	\$	2,700.82			1594.70
		Less 25%	\$ 725.34	\$	675.21			
	Total Cost - List Items		\$ 2,176.02	\$	2,025.62			1196.02

SPECIAL NETT ITEMS

1	Rear n/s tyre (Depreciation)	Damage	\$ 400.00	\$	200.00			Xm
1	Rear n/s wheel rim	Damage	\$ 900.00	\$	900.00			600
	Total Cost - Special Nett items		\$ 1,300.00	\$	1,100.00			

600

Total cost of parts

\$ 3,476.02 \$ 3,800.82

SCL APPRAISER PTE LTD

Vehicle Registration No.: SMG 2554 P

Our Ref No.: TRI/04/2301/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 3,476.02	\$ 3,800.82

LABOUR

1	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 300.00	\$ 240.00 ⁶⁰
2	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 ³⁰
3	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 800.00	\$ 500.00 ⁴⁰⁰
4	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 750.00	\$ 660.00 ⁵⁰⁰ 990

GRAND TOTAL

\$ 5,426.02	\$ 5,260.82
--------------------	--------------------

1196.02
 600
 990

 2786.02
 4582200
 4 days

C L APPRAISER PTE LTD

Vehicle Registration No.: SMG 2554 P

Our Ref No.: TRI/04/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 4,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser