

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Row In 27/6
Survey 28/6
26 June 2024

Estimate No. : b1 70264
Date Estimated : 24/06/2024
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Mui Hong
106 Westwood Crescent

Singapore 648797

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJL8848L	WBAKR020600S46379	18/07/2017	X5 xDrive35i	150595

DESCRIPTION

To tow accident vehicle to PML workshop.

To replace bonnet, front bumper, front left fender, air duct, support, side mirror left assy, wheel arch, make good front left door and attachments. 850

To respray bonnet, front bumper, front left fender, wheel arch, front left door, side mirror cover and affected areas.

To carry out body cavity preservation.
(Per panel). 2x

To check electrical wiring system and lighting at the frontsection for proper function.

To replace left headlamp.

To replace left fog lamp including remove attachments to facilitate repair and conduct check for proper function.

To replace front PDC sensor wire harness including reset and conduct check for proper function.

To remove and install headlight washer and pump assembly to facilitate repairs.

Sundries.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

150.00

4,675.00

4,702.00

236.00

177.00

481.00

266.00

266.00

531.00

150.00

Total Labour 1: 11,634.00

DESCRIPTION

C-CLIP NUT SELF-LOCKING
BONNET

QTY	PRIC
20	1.00
1	3,024.65

VALUE

20.00

3,024.65

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 70264
Date Estimated : 24/06/2024
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJL8848L	WBAKR020600S46379	18/07/2017	X5 xDrive35i	150595

DESCRIPTION	QTY	PRIC	VALUE
BONNET LH HINGE	1	143.40	un X 143.40
Supporting strut left	1	1,166.40	un X 1,166.40
FRT SHOCK ABSORBER	1	92.95	de 92.95
GRILL SIDE CLOSED LH	1	98.90	de 98.90
TRIM GRILLE SIDE LH (PURE EXCELLENC	1	102.35	de 102.35
LH COVER SPRAY NOZZLE PRIMED	1	62.75	de 62.75
FRT BUMPER PANEL PRIMED (PDC/CAM/SR	1	1,747.70	de 1,747.70
LOWER TRIM PANEL (PDC/SCHWARZ)	1	325.40	dis 325.40
PLUG	20	1.60	rel 32.00
FRT LH GRILLE (PURE EXCELLENCE)	1	185.95	un X 185.95
FRT RH GRILLE (PURE EXCELLENCE)	1	185.95	un X 185.95
EMBLEM GROMMET	X 2	0.95	rel 0.95
BMW PLAQUE WITH ADHESIVE FILM	1	75.80	rel 75.80
LH MIRROR GLASS HEATED WIDE ANGLE	1	237.30	dis 237.30
LH OUTSIDE MIRROR COVER CAP PRIMED	1	167.20	rel 167.20
LH EXTERIOR MIRROR W/O GLASS HEATED	1	1,519.05	cur 1,519.05
V STRUT LEFT	1	64.05	un X 64.05
SUPPORT HEADLIGHT LH	1	180.10	dis 180.10
MODULE CARRIER LH	1	156.60	cur 156.60
LH SIDE PANEL CENTRE BRACKET	1	44.15	cur 44.15
FRT LH REINFORCEMENT SIDE PANEL	1	97.00	ht 97.00
FRT LH SIDE PANEL	1	1,436.35	bl 1,436.35
ENGINE COMPARTMENT SHIELDING FRT	1	391.95	un X 391.95
FRT ENGINE HOOD SEALING	1	64.05	un X 64.05
LH ENGINE HOOD SEALING	1	36.30	un X 36.30
FRT LH WHEEL WELL TRIM PCS PRIMED 1	1	312.10	de 312.10
FRONT LEFT Repair wiring	1	757.60	un X 757.60
Fanfare horn	1	93.90	un X 93.90
LH SPRAY NOZZLE	1	201.50	dis 201.50
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	87.60	cut 87.60
LH HEADLIGHT LED TECHNOLOGY	1	5,435.90	cur 5,435.90
LH FOG LIGHT LED	1	501.05	cra un X 501.05
DECOUPING RING PDC TORQUE CONVERTER	X 2	5.55	un X 5.55
ULTRASONIC SENSOR GLACIERSILBER(WA8	1	383.65	un X 383.65

Total Parts : 19,438.10



Tanjiu 97495749 / 62563561
WP 11/7/24 e 445pm
11P Resurvey before paint.
tanjiu e Tanjiu.com
2 day 15 days

Labour 1	:	11,634.00
Parts	:	19,438.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	2,796.49
Grand Total	:	33,868.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **