

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Tlevah had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNN 422B Yr Regn: 2014 / May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz A45 C.D. 1991

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 99018 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1760522J198090

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35R19

R: 235/35R19

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 17/12/24

Survey held at

J L Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

to ALG

COE Expiry : 29/05/2034

Estimate given during : Yes (✓)
1st Survey : No ()

MV :

PV :

Nett :

769.2

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Survey Fee:

Transportation:

S + R.S. \$

Photos

Others

Report Format:

Report Form / L.P.F. ()

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 16.12.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNN422B**
MODEL : **MERCEDES BENZ A45**
DATE OF ACCIDENT : 26.11.2024
TIME OF ACCIDENT : 20:00 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>born</i>	1	\$ 1,735.00	\$ 1,735.00
2	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 35.00	\$ 35.00
3	REAR BUMPER SENSOR <i>1 piece damaged</i>	2	\$ 295.00	\$ 590.00
4	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 65.00	\$ 260.00
5	REAR BUMPER CORNER GRILLE GARNISH RH <i>new</i>	1	\$ 216.30	\$ 216.30
6	REAR BUMPER CORNER INNER GARNISH RH <i>new</i>	1	\$ 165.30	\$ 165.30
7	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 140.00	\$ 280.00
8	REAR BUMPER BRACKET (CENTER) <i>Antenna</i>	2	\$ 170.00	\$ 340.00
9	REAR BUMPER BRACKET (TOP) <i>Antenna</i>	1	\$ 365.00	\$ 365.00
10	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 95.00	\$ 190.00
11	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 760.00	\$ 760.00
12	TAILLAMP <i>Rt Antenna</i>	2	\$ 958.00	\$ 1,916.00
13	REAR FENDER COWLING <i>new</i>	2	\$ 280.00	\$ 560.00
14	REAR END PANEL <i>new</i>	1	\$ 1,340.00	\$ 1,340.00
15	REAR BUMPER EXHAUST CHROME PIPE <i>new</i>	1	\$ 496.20	\$ 496.20

TOTAL PRICE \$ 9,248.80
LESS 10% \$ 924.88
SUB TOTAL PRICE \$ 8,323.92

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNN422B**
 MODEL : **MERCEDES BENZ A45**
 DATE OF ACCIDENT : 26.11.2024
 TIME OF ACCIDENT : 20:00 HOURS

1	REAR BUMPER CLIP <i>ph</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
2	REAR BUMPER DEFFUSER (CARBON FIBER) <i>ut</i>	1	\$ 2,500.00	\$ 2,500.00	<i>1260</i>
3	REAR FENDER COWLING CLIP (SET) <i>ph</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
4	REAR FENDER INNER TRIM CLIP (SET) <i>ph</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
5	REAR END PANEL TOP GARNISH CLIP (SET) <i>ph</i>	1	\$ 60.00	\$ 60.00	<i>+</i>

TOTAL \$ 2,810.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>250</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>250</i>
3	TUFF COAT	\$ 350.00	<i>+</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>+</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 180.00	<i>+</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 580.00	<i>x</i>

TOTAL

\$4,340.00

TOTAL PARTS COST : \$ 11,133.92
 TOTAL LABOUR COST : \$ 4,340.00
 TOTAL REPAIR COST : \$ 15,473.92

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

LKK Auto Consultancy Please notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Two party survey is required
- Any replacement item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date:

Adnan
17/12/24
03 Days