

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600f

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SMD1212Z

NOT Notified
1/10/18 @ 8500h
Recovery After Paint
5 days

No.	Qty	Nett Items			
1	1	Rear bumper	\$ Bu	773.00	✓
2	2	Rear bumper side chrome	\$ nu	330.00	✓
3	2	Rear bumper side reflector	\$ lu	114.00	X
4	2	Rear bumper reverse sensor	\$ cu	584.80	✓
5	2	Rear bumper side retainer	\$ lu	57.00	X
6	2	Taillamp	\$ cu	1,830.20	✓
7	1	Rear tailgate	\$ lu	1,169.10	✓
8	1	Rear tailgate top spoiler	mg cm \$	890.90	✓
9	1	Rear tailgate top centre "H" logo	\$ nu	29.80	✓
10	1	Rear tailgate LH "ODYSSEY" emblem	\$ nu	45.80	✓
11	1	Rear tailgate top centre outer handle/garnish	\$ mg cm	318.90	✓
12	2	Rear tailgate side lamp	\$ cm	910.00	✓
13	1	Rear tailgate reverse camera	\$ lu	567.80	✓
14	1	Rear tailgate windscreen glass	shatter \$	1,388.50	✓
15	1 set	Rear tailgate windscreen glass moulding	\$ nu	268.00	✓
16	1	Rear tailgate wiper arm	\$ lu	58.00	X
17	1	Rear tailgate wiper blade	\$ lu	46.80	X
18	1	Rear tailgate wiper motor	\$ lu	385.00	✓
19	1	Rear tailgate top lock	\$ nu	302.40	✓
20	1	Rear tailgate lower lock catch	\$ lu	30.50	X
21	1	Rear tailgate inner trim board	\$ lu	375.00	✓
22	1 set	Rear tailgate inner trim board clips	\$ nu	80.00	✓
23	1	Rear tailgate weatherstrip	92-505N \$	185.00	505N
24	1	Rear end panel	\$ lu	503.00	X
25	1	Rear end panel top garnish	\$ mg cm	132.50	✓
Total :			\$	11,376.00	

201

Special Nett Items

26	1 set	Rear tailgate windscreen sealant	\$ nu	60.00	405N
27	1	Rear tailgate windscreen tinted film	\$ nu	250.00	1805N
28	1 set	Rear tailgate windscreen Incar security camera	mis \$	650.00	4005N
29	1	Rear number plate	\$ lu	50.00	X
30	1 set	Rear end panel sealant	\$ nu	60.00	X
Total :			\$	1,070.00	

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00	500
2	To putty and spray Spray Paintings charges.	\$	1,200.00	800
3	To check wirings & lightings.	\$	40.00	201
4	To remove, refix & reset reverse camera & reverse sensor.	\$	150.00	801
5	To remove, refix rear windscreen glass.	\$	140.00	1201
6	To remove, refit rear tailgate fittings.	\$	80.00	601
7	To remove, refix rear upholstery & attachments.	\$	120.00	601

	\$	80.00	3d
Total :	\$	2,810.00	

Total Parts and Labour : \$ 15,256.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: