

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A1423006685/U2a3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDJ15H

at Workshop m/s speedwreck

of

Insured: G13D47694

Policy No.

Claims No.

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8140K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 27485584

Veh No: SDJ15H Yr Regn: 09/10/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or IA / V6 ES

Make: Porsche Cayenne c.c. 3598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 142450 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP1222922DLA05735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/50 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 03/07/23 D.O.I. 4/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 207 18k.

5/7/23 col unk. 30-11-2031
L/S 43900 in hand work

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format : _____

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

TOTAL

SPEEDWERKZ PRIVATE LIMITED

6 Kaki Bukit Avenue #01-73, AUTOBAY, Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

not Auland
4/7/23
4/5 @ 3900
2 days

VEHICLE NUMBER: SDJ15H

MAKE & MODEL: PORSCHE CAYENNE V6 E5 TIP

DOA: 03/07/2023

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BONNET	1	\$1,980.00	11 X
FRONT BUMPER 2665	1	\$2,995.50	Dis -
FRONT BUMPER AIR GRILLE 1111	1	\$425.00	one -
FRONT BUMPER LAMP @ 890.00 620	2	\$1,780.00	1/2 sn 1 o/s one 1/2
FRONT BUMPER LAMP COVER @ 415.00	2	\$830.00	11 X
FRONT BUMPER HEAD LAMP NOZZLE COVER @ 475.00	2	\$950.00	11 X
FRONT BUMPER HEAD LAMP NOZZLE @ 235.00	2	\$470.00	11 X
FRONT BUMPER SPOUNGE sponge 266	1	\$345.00	Tom -
FRONT BUMPER REINFORCEMENT 715	1	\$785.00	Bent -
HEAD LAMP @ 2950.00	2	\$5,900.00	11 X
FRONT BUMPER PARKING SENSOR @ 345.00	4	\$1,380.00	11 X
FRONT BUMPER SIDE RETAINER @ 215.00	2	\$430.00	11 X
AIRCOND CONDENSER	1	\$1,650.00	11 X
FRONT SUPPORT PANEL	1	\$1,980.00	11 X
		\$21,900.50	
		Less 5% (102)	
		\$1,095.03	
Sub Total		<u>\$20,805.48</u>	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT NUMBER PLATE	1	\$45.00	11 X
FRONT BUMPER CLIP	1	\$100.00	11 50
Sub Total		<u>\$145.00</u>	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
CHECK WIRING		\$150.00	20
REMOVE AND REFIX AIRCOND CONDENSER		\$150.00	11 X
REMOVE AND REFIX RADIATOR		\$120.00	11 X
KNOCK DENTS ON FRONT DAMAGE PORTION, CUT, WELDING AND RENEW PARTS		\$1,800.00	300
RESPRAY PAINTING		\$1,600.00	300
Sub Total		<u>\$3,820.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total \$24,770.48

P- 4691
102
4221.9
50
620
4891.9
3813