

ASS. REC. BY:

REF: AG21


Kenneth

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8184k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 1B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PCX 3E Yr Regn: 07, 24
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: BYD Seal C.C. _____
Colour: Black A/C: Insured / Std / NI / NA
Sp.Reading: 8643 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: LGXCH6CD3R-2127806
Gen. Cohd: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 235/45R19
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental

Front: _____ Rear: _____
R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 12/12/24 D.O.I. 19/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BZ, Spare parts not available in local market at the moment.

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

S - RS. SI

F. P. S.

Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896
HP: 98888885

Not Authen
Rehmy B4pain

Estimation

Date:

18/12/2024

Vehicle:

SCX3E

Make / Model:

BYD SEAL PREMIUM

No.	Description	Unit	Unit Price	Amount
1	Parts Replacement:			
2	REAR BUMPER	1	\$ 1,798.00	\$ 1,798.00
3	REAR BUMPER LOWER DIFUUSER	1	\$ 1,025.00	\$ 1,025.00
4	REAR BUMPER SIDE RETAINER	2	\$ 159.00	\$ 318.00
5	REAR BUMPER LOWER	1	\$ 721.00	\$ 721.00
6	REAR BUMPER REFLECTOR	2	\$ 312.00	\$ 624.00
7	REAR BUMPER REINFORCEMENT	1	\$ 512.00	\$ 512.00
8	REAR BUMPER CENTRE BRACKET GARNISH	1	\$ 358.00	\$ 358.00
9	REAR BUMPER REVERSE CAMERA	1	\$ 1,125.00	\$ 1,125.00
10	REAR BUMPER REVERSE SENSOR	4	\$ 321.00	\$ 1,284.00
11	REAR BUMPER NUMBER PLATE LAMP	2	\$ 251.00	\$ 502.00
12	REAR BUMPER UNDER COVER	1	\$ 489.00	\$ 489.00
13	BOOTLID	1	\$ 2,110.00	\$ 2,110.00
14	BOOTLID LOCK	1	\$ 412.00	\$ 412.00
15	BOOTLID INNER TRIM	1	\$ 512.00	\$ 512.00
16	BOOTLID EMBLEM 'BYD SEAL'	1	\$ 198.00	\$ 198.00
17	BOOTLID EMBLEM 'BYD'	1	\$ 211.00	\$ 211.00
18	BOOTLID WEATHERSTRIP	1	\$ 259.00	\$ 251.00
19	BOOTLID REFLECTOR	1	\$ 1,025.00	\$ 1,025.00
20	REAR END PANEL TOP GARNISH	1	\$ 351.00	\$ 351.00
21	REAR END PANEL	1	\$ 689.00	\$ 689.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification is allowed

Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

S/Nett items:

1	REAR BUMPER CLIPS SET	1	\$ 50.00	\$ 50.00
2	BOOTLID INNER TRIM CLIPS	1	\$ 50.00	\$ 50.00
				\$ 100.00

Labour to:

Acknowledged by Repairer

Signature:

Date:

1	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
2	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
3	TO CHECK ELECTRICAL WIRING/RESET TROUBLE CODE	1	\$ 300.00	\$ 300.00
4	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR	1	\$ 100.00	\$ 100.00
5	RESET FAULT CODE	1	\$ 400.00	\$ 400.00
6	REMOVE AND REFIT BOOTLID MECHANISM	1	\$ 200.00	\$ 200.00
7	REMOVE AND REFIT ALL UPHOLSTERY TO PROCEED REPAIR	1	\$ 300.00	\$ 300.00
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00

Parts Replacement Amount

\$ 13,889.25

Total Amount for Labour

\$ 3,100.00