

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 18.04.2023

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNB1200G**
MODEL : **AUDI R8**
DATE OF ACCIDENT : 17.04.2023
TIME OF ACCIDENT : 14:40 HOURS

WUA 22242884004457
vecon.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Cracked.</i>	1	\$ 8,775.00	\$ 8,775.00
2	REAR BUMPER SIDE GRILLE <i>RH ut.</i>	2	\$ 1,884.00	\$ 3,768.00
3	REAR BUMPER CENTER UPPER COVER <i>new</i>	1	\$ 685.30	\$ 685.30
4	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 89.40	\$ 178.80
5	REAR BUMPER LOWER DIFFUSER <i>new</i>	1	\$ 1,956.00	\$ 1,956.00
6	REAR BUMPER LOWER DIFFUSER GRILLE <i>Cracked</i>	1	\$ 486.30	\$ 486.30
7	REAR BUMPER LAMP <i>Cracked</i>	1	\$ 586.30	\$ 586.30
8	REAR BUMPER SENSOR <i>Damaged</i>	2	\$ 482.40	\$ 964.80
9	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 60.85	\$ 243.40
10	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 952.30	\$ 952.30
11	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 4,662.00	\$ 4,662.00
12	REAR BUMPER CENTER BRACKET <i>Cracked</i>	1	\$ 953.20	\$ 953.20
13	REAR EXHAUST CHROME PIPE RH <i>new</i>	1	\$ 1,356.00	\$ 1,356.00
14	REAR EXHAUST INSULATOR <i>new</i>	2	\$ 588.20	\$ 1,176.40
15	REAR FENDER COWLING <i>new</i>	2	\$ 365.40	\$ 730.80
16	TAIL LAMP <i>Cracked.</i>	2	\$ 5,445.00	\$ 10,890.00

23344.20
2224.48

TOTAL PRICE \$ 38,364.60
LESS 5% \$ 1,918.23
SUB TOTAL PRICE \$ 36,446.37

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 200.00	\$ 200.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNB1200G**
 MODEL : **AUDI R8**
 DATE OF ACCIDENT : 17.04.2023
 TIME OF ACCIDENT : 14:40 HOURS

2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>50</i>
3	REAR SPOILER (CARBON FIBER) <i>new</i>	1	\$ 4,500.00	\$ 4,500.00	<i>x</i>
4	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00	<i>x</i>

50

TOTAL \$ 5,310.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,400.00	<i>300</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>50</i>
4	WIRING AND BULB CHECK	\$ 250.00	<i>50</i>
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 350.00	<i>80</i>
6	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 380.00	<i>x</i>
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 1,200.00	<i>x 200</i>

1480

TOTAL \$ 6,630.00

Adrian

2/5 20/04/23.

04 Days

ESTIMATE REPORT

TOTAL PARTS COST : \$ 41,756.37
 TOTAL LABOUR COST : \$ 6,630.00
 TOTAL REPAIR COST : \$ 48,386.37

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY:
 the Repairer of the following:
 • To display damaged parts during resurvey
 • To provide a written confirmation
 • To provide a written confirmation
 • To provide a written confirmation

IRENE

SERVICE ADVISOR

IRNE

HP : 8297 9787

total: 23754.49

4/5 19K.

19K.