

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMD 2786C

| REPLACEMENT OF PARTS |                                   |                      |                        |                   |  |
|----------------------|-----------------------------------|----------------------|------------------------|-------------------|--|
| Qty                  | Description of Parts              | Condition            | Workshop Estimate (\$) | Our Adjusted (\$) |  |
| 1                    | FRONT BUMPER FASCIA               | TORN                 | \$1,844.50             | \$980.00          |  |
| 1                    | FRT BUMPER CORNER ARCH GARNISH RH | CUT/DEFORMED         | \$285.10               | \$199.00          |  |
| 1                    | FOG LAMP RH                       | CRACKED              | \$485.50               | \$348.00          |  |
| 1                    | FOG LAMP GARNISH RH               | CRACKED              | \$289.30               | \$289.30          |  |
| 1                    | FOG LAMP CHROME BLADE RH          | NOT NECESSARY        | \$580.20               | \$0.00            |  |
| 1                    | SET FRONT BUMPER CLIP             | NECESSARY            | \$80.00                | \$30.00           |  |
| 1                    | FRONT BUMPER REINFORCEMENT        | NOT NECESSARY        | \$712.80               | \$0.00            |  |
| 1                    | HEADLAMP RH                       | NOT NECESSARY        | \$3,150.80             | \$0.00            |  |
| 1                    | HEADLAMP LOWER CHROME BLADE RH    | CRACKED              | \$750.10               | \$435.00          |  |
| 1                    | FRT BUMPER CTR FINISHER (BLACK)   | CRACKED              | \$611.50               | \$517.00          |  |
| 1                    | WASHER TANK                       | DEFORMED             | \$215.30               | \$215.30          |  |
| 1                    | FRONT GRILLE                      | NOT NECESSARY        | \$985.20               | \$0.00            |  |
| 1                    | FRONT GRILLE EMBLEM               | NOT NECESSARY        | \$98.40                | \$0.00            |  |
| 1                    | FRONT BUMPER LOWER SPOILER        | NOT NECESSARY        | \$952.30               | \$0.00            |  |
| 1                    | FRONT SUPPORT PANEL (NPA)         | TO REPAIR SEE LABOUR | \$0.00                 | \$0.00            |  |
|                      | LESS 10.00% DISCOUNT              |                      | (\$1,104.10)           | (\$301.36)        |  |
|                      |                                   |                      | \$9,936.90             | \$2,712.24        |  |

| Labour  |  |                   |  |  |  |
|---|--|-------------------|--|--|--|
| Description of Parts  | Condition Workshop Estimate (\$              | Our Adjusted (\$) |  |  |  |
| TO REMOVE & DISMANTLE DAMAGED PARTS OUT ATTACHEMENT PARTS. TO KNOCK, STR WHERE NECESSARY TO WELD, REFIX, REAL SAME. INCLUSIVE OF THE REPAIR OF FRON | AIGHTEN OUT DENTS DJUST & RESHAPE \$1,200.00 | \$300.00          |  |  |  |
| TO RESPRAY PAINTING ON ALL AFFECTED P<br>PAINT MATERIAL I.E. SAND PAPER, RUBBING<br>THINNER, PAINT, LACQUER ETC                                     |  | \$300.00          |  |  |  |
| TO CHECK WIRINGS AND LIGHTINGS  | \$100.00                                     | \$30.00           |  |  |  |
| TO SUPPLY AND APPLY RUST PROOFING TR<br>AFFECTED PANEL  | EATMENT TO \$80.00                           | \$20.00           |  |  |  |
|   | \$2,780.00                                   | \$650.00          |  |  |  |
| GRAND TOTAL   | \$12,716.90                                  | \$3,362.24        |  |  |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

RECOMMENDED COST OF REPAIRS \$3,362.24

Report Ref No: CS1/LPM24120212/Eqh3e2

MARKET VALUE: \$120,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$47,498.00=NETT VALUE: \$72,502.00

## CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.