

ESTIMATE OF REPAIR

Veh# SLL7853D

Accident Date : 2/5/2023

Location : ROUNDABOUT NEAR MARYMOUNT RD (AMK) EXIT

Model:

SUBARU XV
(10/3/2017 - 9/3/2027)

3P:

SMH72X (UOI)

TP WOJ.

Celine.

JF1G93KCSH920336

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front sport rim RH <i>old</i>	1,020.00	580 (50)	
2	1 pc	Front tyre RH <i>old</i>		350.00	180 (50)
3	1 pc	Front shock absorber RH <i>new</i>	324.00	+	
4	1 pc	Front shock absorber mounting RH <i>new</i>	95.00	+	
5	1 pc	Front lower arm RH <i>Best</i>	644.60	-545	
6	1 pc	Front knuckle arm RH <i>Best</i>	285.10	-	
7	1 pc	Front knuckle arm bearing RH <i>Best</i>	346.60	-	
8	1 pc	Front linkage RH <i>new</i>	92.40	x.	
9	1 pc	Front steering tie rod end RH <i>new</i>	91.20	+	
10	2 pcs	Front headlamp R/L <i>R/L changed</i>	1,962.40	981.20	
11	2 pcs	Front headlamp side bracket R/L <i>new</i>	97.70	x	
12	1 pc	Front grille <i>changed</i>	574.10	-	
13	1 pc	Front grille emblem logo <i>new</i>	84.60	-	
14	1 pc	Front grille upper frame bracket <i>changed</i>	42.20	-	
15	1 set	Front grille clip <i>new</i>		40.00	20
16	1 pc	Front bumper <i>Distorted</i>	683.65	-	
17	2 pcs	Front bumper side retainer R/L <i>R/L Best</i>	36.00	18	
18	1 pc	Front bumper foglamp RH <i>changed</i>	326.65	-	
19	1 pc	Front bumper foglamp cover RH <i>old</i>	102.72	-	
20	1 set	Front bumper clip <i>new</i>		50.00	30
21	1 pc	Front fender RH <i>Dented</i>	336.00	-	
22	1 pc	Front fender arch garnish RH <i>old</i>	216.60	-	
23	2 pcs	Front fender inner shield R/L <i>R/L torn</i>	259.20	-	
24	2 sets	Front fender inner shield clip R/L <i>new</i>		100.00	60
25	1 pc	Air cleaner box <i>new</i>	144.10	x.	
Sub Total:			7,764.82	540.00	0.00
20%			20%	0%	10%
After Less %:			6,211.86	540.00	0.00
Labour					
1		To remove & refix accident damaged parts & realign accident affected area.	1,000.00	800	
2		To spray paint accident affected area.	1,200.00	500	
3		To remove & refix front under carriage suspension.	250.00	200	
4		To computerise wheel alignment.	120.00	80	
5		To check wiring & headlamp focus.	50.00	30	
6		To rust proof accident affected area.	100.00	40	
Sub Total:			2,720.00		
Total:			9,471.86		
After Less 20%:			7,577.48		

LKK Auto Consultants being party to the Repair of the following:

- To rectify before after body painting
- To dislay damage parts during resurvey
- Parts prices are subject to information
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Chan San Choon
Director/Repairer
DipEng, AAE, MIMI, MSAE (Aust)

Date:



Adnan Lg
h/s: 04/05/23

66 Days.

total: 6161.29

h/s: 4.9K.

1450