

ASSIGNMENT

From: _____ Date: _____

Estim: at cost

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at Work / Shop / ms

of _____

Insured: _____

Policy No. _____

Claim's No. _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 9011A Yr Regn: 2018 / June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Voxy C.D. 1797

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 619531 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR800317680

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R16

R: 195/65 R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 16/12/24

Survey held at HD Perfect

Des. of Damages: Frt / Rear / O/S / N/S U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

TP AIG

COE Expiry

Estimate given during : Yes (✓)
1st Survey : No ()

MV :

PV :

Nett :

134J

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Report Format: _____


Report Date: _____

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 16.12.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMA9011A**
MODEL : **TOYOTA VOXY**
DATE OF ACCIDENT : 15.12.2024
TIME OF ACCIDENT : 14:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT LH <i>De-bent</i>	1	\$ 1,125.30	\$ 1,125.30
2	SLIDING DOOR LH <i>De-bent</i>	1	\$ 1,585.00	\$ 1,585.00
3	SLIDING DOOR STRIP SENSOR LH <i>new</i>	1	\$ 971.50	\$ 971.50
4	SLIDING DOOR OUTER STRIP LH <i>new</i>	1	\$ 1,300.00	\$ 1,300.00
5	SLIDING DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 487.10	\$ 487.10
6	SLIDING DOOR AUTO SYSTEM MOTOR <i>new</i>	1	\$ 1,993.90	\$ 1,993.90
7	SLIDING DOOR STICKER (BLACK) (SET) <i>new</i>	1	\$ 210.00	\$ 210.00
8	SLIDING DOOR FRONT INNER LOCK LH <i>new</i>	1	\$ 618.10	\$ 618.10
9	SLIDING DOOR INNER TRIM LH <i>new</i>	1	\$ 1,897.40	\$ 1,897.40
10	SLIDING DOOR FRAME WEATHER STRIP LH <i>new</i>	1	\$ 577.40	\$ 577.40
11	SLIDING DOOR STEP PANEL LH <i>new</i>	1	\$ 633.70	\$ 633.70
12	SLIDING DOOR STEP PANEL GARNISH LH <i>new</i>	1	\$ 498.80	\$ 498.80
13	SLINDING DOOR WEATHERSTRIP LH <i>new</i>	1	\$ 298.00	\$ 298.00
14	SLIDING DOOR BACK INNER LOCK <i>new</i>	1	\$ 524.30	\$ 524.30
15	SLINDING DOOR LOWER ROLLER LH <i>new</i>	1	\$ 285.00	\$ 285.00
16	SLINDING DOOR LOCK CATCH LH <i>new</i>	1	\$ 78.00	\$ 78.00
17	REAR FENDER LH <i>De-bent</i>	1	\$ 850.00	\$ 850.00
18	REAR FENDER ARCH SEAL LH <i>new</i>	1	\$ 138.10	\$ 138.10
19	REAR FENDER LOWER GUARD LH <i>new</i>	1	\$ 148.10	\$ 148.10
20	REAR FENDER COWLING LH <i>new</i>	1	\$ 158.10	\$ 158.10
21	REAR FENDER INNER SHIELD LH <i>new</i>	1	\$ 218.10	\$ 218.10
22	REAR FENDER GLASS WITH MOULDING <i>new</i>	1	\$ 930.00	\$ 930.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMA9011A**
 MODEL : **TOYOTA VOXY**
 DATE OF ACCIDENT : 15.12.2024
 TIME OF ACCIDENT : 14:50 HOURS

23	REAR ABS SENSOR LH <i>new</i>	1	\$ 398.00	\$ 398.00	+
24	REAR SHOCK ABSORBER LH <i>new</i>	1	\$ 395.00	\$ 395.00	+
25	REAR WHEEL HUP WITH BEARING LH <i>old</i>	1	\$ 995.00	\$ 995.00	+
26	REAR AXLE <i>new</i>	1	\$ 3,150.00	\$ 3,150.00	+
27	REAR BUMPER <i>Delrud</i>	1	\$ 1,450.00	\$ 1,450.00	+
28	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 78.00	\$ 156.00	+
29	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 78.00	\$ 156.00	+

TOTAL PRICE \$ 22,225.90
 LESS 25% \$ 5,556.48
SUB TOTAL PRICE \$ 16,669.43

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	SLIDING DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
2	REAR FENDER SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	60
3	REAR FENDER COWLING CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	REAR FENDER INNER TRIM CLIP <i>new</i>	1	\$ 60.00	\$ 60.00	+
5	REAR FENDER INNER SHIELD CLIP LH (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
6	REAR FENDER GLASS SOLAR FILM <i>new</i>	1	\$ 300.00	\$ 300.00	+
7	REAR FENDER GLASS INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	+
8	REAR FENDER GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
9	REAR WHEEL TYRE LH <i>new</i>	1	\$ 450.00	\$ 450.00	+
10	REAR WHEEL RIM LH <i>cut</i>	1	\$ 1,200.00	\$ 1,200.00	600
11	WHEEL CAP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	+
12	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
13	STEP PANEL GARNISH CLIP <i>new</i>	1	\$ 60.00	\$ 60.00	+
14	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	+

TOTAL \$ 2,630.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMA9011A**
 MODEL : **TOYOTA VOXY**
 DATE OF ACCIDENT : 15.12.2024
 TIME OF ACCIDENT : 14:50 HOURS

3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 150.00	30
5	REMOVE AND REFIX FUEL TANK	\$ 120.00	60
6	TRANFER FRONT DOOR MECHANISM RH	\$ 80.00	40
7	REMOVE & REINSTALL FRONT WINDOW GLASS RH	\$ 60.00	40
8	REMOVE AND REFIX REAR FENDER QUARTER GLASS RH	\$ 120.00	X
9	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
10	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 550.00	X
11	TO PRESS REAR WHEEL BEARING	\$ 80.00	X
12	FOUR WHEEL ALIGNMNET	\$ 120.00	80
13	TRANFER SLIDING DOOR MECHANISM RH	\$ 80.00	60
14	REMOVE, REFIX AND RESET SLIDING DOOR AUTO SYSTEM	\$ 350.00	X
15	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 60.00	X
16	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
17	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
18	RESET ABS LIGHT	\$ 350.00	X.

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMA9011A**
MODEL : **TOYOTA VOXY**
DATE OF ACCIDENT : 15.12.2024
TIME OF ACCIDENT : 14:50 HOURS

19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
----	---	-----------	---

TOTAL \$6,800.00

TOTAL PARTS COST : \$ 19,299.43
TOTAL LABOUR COST : \$ 6,800.00
TOTAL REPAIR COST : \$ 26,099.43

Adrian G
2/5 16/12/24.
06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: