

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

☒	☒
N/S	O/S

Sal. or Market Value: 4135K
 IDAC Accident Rpt. _____ Consistent? : Yes or No
 GIA / PR Seent _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS - WP'
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SMS95245 Yr Regn: 2029 03
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 520I c.c. 1998
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 32259 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAJR12070CD71409
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / SR / STD A/Rim or
 Tyre Size: F: 245/45 R18
 R: ~ ~
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 17/12/24
 Survey held at Performance
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or
Frt N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prell. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Rep. Format: _____
 Lump Sum / L.B.J.: _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Invs (\$) _____
☐ : Weekend (\$) _____
 Survey Fee: _____
 Transportation: _____
 S + RS _____
 Photos _____
 Others _____

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Car In
→ India
16 Dec 2024

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 72117
Date Estimated : 13/12/2024
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS9524S	WBAJR12070CD71409	23/03/2020	520i	28649

DESCRIPTION

To tow accident vehicle to PML workshop.

to tow
invoice ? 150.00

To replace bonnet, front left fender, front bumper, inner support, front wall
air duct, make good front left chassis and attachments.

2400 4,675.00

To respray bonnet, front bumper, front left fender, front left chassis and affected areas.

3221 3,669.00

To replace front left sport rim including 1x wheel balancing.

✓ 94.00

To carry out body cavity preservation.
(Per panel). 2x \$118/panel

✓ 236.00

To replace left headlamp.

✓ 481.00

To replace front pdc sensor wire harness including reset and conduct check for proper function.

172X 266.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

✓ 177.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

✓ 531.00

Sundries.

? 150.00

Total Labour 1: 10,429.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET L=11MM	20	0.55	11.00
ALLOY RIM 8JX18 DOUBLE SPK 634	1	1,141.60	1,141.60
ENGINE SUPPORT LH	1	381.80	381.80
FRT LH SIDE PANEL BRACKET 1	1	45.50	45.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 72117
Date Estimated : 13/12/2024
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS9524S	WBAJR12070CD71409	23/03/2020	520i	28649

DESCRIPTION	QTY	PRIC	VALUE
ALUMINIUM ENGINE HOOD	1	2,734.80	bt 2,734.80
FRT LH SIDE PANEL ALUMINIUM	1	1,020.25	bt 1,020.25
Necessary set mount	1	43.00	ny 43.00
LH GRILLE AIR INLET OPEN (LINES)	1	125.35	cut 125.35
LH PROTECTIVE STRIP LINES (SPORT)	1	76.75	cut 76.75
FRT IMPACT ABSORBER BOTTOM	1	114.45	? 114.45
FRT BUMPER CARRIER	1	790.05	? 790.05
FRT BUMPER BOTTOM CARRIER	1	434.55	? 434.55
LH FOG LAMP SUPPORT	1	123.85	? 123.85
LH GUIDE TOP	1	37.25	? 37.25
LH BUMPER GUIDE	1	17.45	? 17.45
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,510.80	dl 1,510.80
FRT LH GRILLE (M/SPORT)	1	174.40	bne 174.40
PLAQUE 82MM	1	76.55	ny 76.55
GROMMET	1	0.80	ny 0.80
FRT PANEL SUPPORT	1	72.65	? 72.65
LH HEADLIGHT MOUNTING	1	240.00	? 240.00
FRT LH WHEEL ARCH FRT SECTION COVER	1	146.50	? 146.50
LH AIR DUCT BRAKE	1	59.20	? 59.20
AIR FLAPS TOP	1	321.70	? 321.70
AIR FLAP CONTROL ACTIVE TOP	1	102.10	? 102.10
LH BOTTOM COVER	1	81.35	? 81.35
FRT ENGINE BONNET SEAL	1	37.05	? 37.05
RH SEALING SIDE PANEL	1	56.65	? 56.65
FRT BUMPER SET OF CABLES	1	265.10	? 265.10
HORN HIGH PITCH	1	98.70	? 98.70
LH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,144.85	ane 5,144.85
Necessary ring	4	5.65	ny 22.60
PDC SENSOR SOPHISTOGRU II WA90	1	404.25	? 404.25

Total Parts : 15,912.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed	:	10,429.00
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	:	15,912.90
Labour 2	:	0.00
Acknowledged by Repairer	:	0.00
Signature: Total GST @ 9%	:	2,370.77
Date:	:	

Grand Total : 28,712.67



Tanpin 97495749/62563561
WP 17/12/24 23pm
P/P Resurvey before paint
tanpin@lkhauto.com
6-7 days

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **