

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBE5456K/2406101

01th July 2024

The Manager
Motor Claim Department
ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

Date of Accident : 28th June 2024
Location : Steven Road
Third Party Claim Vehicle No : YQ 973 G
Repair Cost For Vehicle No : GBE 5456 K Nissan NV350

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>no / 3-4</i>	1	2,021.80	\$ 2,021.80 ✓
2	Rear boot cover logo <i>SL</i>	1	72.20	\$ 72.20 ✗
3	Rear boot cover emblem 'NV350' <i>ner</i>	1	122.40	\$ 122.40 ✓
4	Rear boot cover emblem 'urvan' <i>ner</i>	1	72.20	\$ 72.20 ✓
5	Rear boot cover windscreen <i>shut</i>	1	1,032.20	\$ 1,032.20 ✓
6	Rear boot cover chrome <i>one</i>	1	596.40	\$ 596.40 ✓
7	Rear boot cover lock <i>Dye / 1/2</i>	1	319.30	\$ 319.30 ✓
8	Rear boot cover latch <i>17</i>	1	56.20	\$ 56.20 ✗
9	Rear boot cover weather stripe <i>SL</i>	1	149.50	\$ 149.50 ✗
10	Rear boot cover damper L&R <i>17</i>	2	240.40	\$ 480.80 ✗
11	Rear boot cover hinge L&R <i>17</i>	2	70.30	\$ 140.60 ✗
✗ 12	Rear boot cover mirror <i>NZ</i>	1	124.90	\$ 124.90 ✗
13	Tail lamp L&R <i>1/5 one</i>	2	235.30	\$ 470.60 <i>1 pc</i>
14	Rear bumper fascia <i>1/2</i>	1	743.00	\$ 743.00 ✓
15	Rear bumper reinforcement beam <i>2er</i>	1	231.70	\$ 231.70 ✓
16	Rear bumper side retainer L&R <i>17</i>	6	18.00	\$ 108.00 ✓
				\$ 6,741.80

not Ireland
no car
2/3
3/7/24
1/5 # 5200
4 days.

not itar

102

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBE5456K/2406101

01th July 2024

S. Woff				
No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 6,741.80
17	Rear bumper clips (s/nett) <i>nei</i>	1 set	50.00	\$ 50.00 <i>30</i>
18	Rear end panel (s/nett) <i>DD/2nd</i>	1	163.80	\$ 163.80 <i>—</i>
19	Rear bumper parking sensor (s/nett) <i>see</i>	1	380.00	\$ 380.00 <i>X</i>
20	Rear boot third brake light (s/nett) <i>11</i>		235.60	\$ 235.60 <i>X</i>
21	Rear boot cover sticker '70km/hr' (s/nett) <i>nei</i>	1	28.00	\$ 28.00 <i>10</i>
22	Rear boot windscreen sealant (s/nett) <i>nei</i>	1	60.00	\$ 60.00 <i>40</i>
23	Rear end panel sealer(s/nett) <i>nei</i>	1 set	80.00	\$ 80.00 <i>30</i>
24	Rear number plate (s/nett) <i>see</i>	1 set	50.00	\$ 50.00 <i>X</i>
				\$ 7,789.20

Labour Charges :-

	Amounts	
Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts, straighten & re-align body	\$ 880.00	<i>700</i>
Tuff-kote on damage parts	\$ 80.00	<i>50</i>
Spray painting on damage parts	\$ 1,080.00	<i>680</i>
Remove & refix rear windscreen glass	\$ 120.00	<i>—</i>
Remove & refix rear bumper sensor	\$ 80.00	<i>30</i>
Check all lighting after repairs	\$ 35.00	<i>20</i>
Labour Charge	\$ 2,275.00	
Total Amount	\$ 10,064.20	

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5186
102
P-4667.40
S.W-273.80
+ 1600
6544.20
202
5232.