

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Xiao Tong

Vehicle Number : SJW4000J
Vehicle Model : HONDA VEZEL
Accident Date : 14.12.2024
Original Reg Date : 24.03.2015

Date : 17.12.2024
Chassis : RU11017007
TP Ins. III

ESTIMATE

1	1 pc	Tailgate <i>Disturbed</i>		1,723.20	1100
2	1 pc	Tailgate Outer Garnish <i>Cracked</i>		398.80	✓
3	1 pc	Tailgate Outer Garnish Clips <i>in</i>		30.00	20
4	1 pc	Tailgate Badge <i>new</i>		98.60	✓
5	1 pc	Tailgate Emblem VEZEL <i>new</i>		95.70	✓
6	2 pc	Tailgate Lamps <i>Cracked</i>	528.70	1,057.40	850
7	1 pc	Tailgate Lamp Inner Sealer <i>new</i>		40.00	+
8	1 set	Tailgate Lamp Clips <i>new</i>		30.00	+
9	2 pcs	Tailgate Stopper <i>new</i>	25.00	50.00	+
10	1 pc	Tailgate Pocket Handle <i>new</i>		65.80	+
11	1 pc	Tailgate Inner Trim <i>Cracked</i>		485.60	325
12	1 set	Tailgate Inner Trim Clips <i>in</i>		30.00	✓
13	1 pc	Tailgate Inner Lock <i>Jammed</i>		345.80	265
14	1 pc	Tailgate Lock Catch <i>new</i>		46.00	+
15	1 pc	Tailgate Weatherstrip <i>cut</i>		198.70	✓
16	2 pcs	Tailgate Hinges <i>new</i>	68.00	136.00	+
17	2 pc	Tailgate Absorbers <i>new</i>	198.60	397.20	+
18	1 set	Rear Windscreen Moulding <i>new</i>		165.80	✓
19	1 pc	Rear Windscreen Inner Seal		60.00	✓
20	1 pc	Rear Windscreen <i>new</i>		698.70	+
21	1 pc	Rear Bumper <i>Deformed</i>		855.60	745
22	1 pc	Rear Bumper Side Retainers <i>new</i>		90.60	+
23	1 pc	Rear Bumper Attachment Retainers <i>new</i>		86.20	+
24	1 set	Rear Bumper Clips <i>new</i>		50.00	30
25	2 pcs	Rear Bumper Reflectors <i>Bit cracked</i>	98.90	197.80	98.90
26	1 pc	Rear Bumper Under Cover <i>Deformed</i>		196.00	✓
27	1 set	Rear Bumper Under Cover Clips <i>in</i>		30.00	✓
28	2 pc	Rear corner Bumper <i>Repair</i>	278.90	557.80	+
29	1 pc	End Panel <i>Deformed</i>		695.00	585
30	1 pc	End Panel Top Trim <i>Deformed</i>		198.30	✓
31	1 set	End Panel Top Trim Clips <i>in</i>		30.00	20
32	1 pc	Spare Tyre Panel <i>Deformed</i>		1,245.00	1120
33	1 pc	Spare Tyre Panel Top Board <i>Deformed</i>		462.00	359
34	1 pc	Spare Tyre Panel Top Tool Sponge <i>Cracked</i>		351.00	✓
35	1 pc	Rear Key Antena Sensor <i>new</i>		145.80	✓

36	1 pc	Alarm Sensor Speaker <i>Oruld</i>		150.00	<i>✓</i>
37	2 pc	Taillamp <i>cut</i>	680.90	1,361.80	<i>→ 950</i>
38	2 set	Taillamps Clips <i>for n</i>		30.00	<i>+</i>
39	2 pc	Rear Fender Inner Trim <i>lit Perled</i>	387.50	775.00	<i>→ 387.50</i>
40	1 set	Rear Fender Inner Trim Clips <i>n</i>	30.00	60.00	<i>→ 30</i>
41	2 pc	Rear fender inner cowling <i>new</i>	187.20	374.40	<i>+</i>
42	2 set	Rear fender inner cowling clips <i>new</i>	30.00	60.00	<i>+</i>
43	2 pc	Rear Fender Arch Garnish <i>LH Oruld</i>	208.30	416.60	<i>+ 208.30</i>
44	2 pcs	Rear Fender Arch Garnish Clips <i>n</i>		30.00	<i>+ 15,</i>
				14,602.20	
				Less 20%	
				2,920.44	
				11,681.76	

9091.60
73273.28

Special Nett

1	1 pc	Rear Windscreen Sealant <i>new</i>		60.00	<i>✓</i>
2	1 pc	Rear Number Plate with Cover <i>new</i>		50.00	<i>+</i>
3	1 set	Reverse Sensor <i>2nd</i>		250.00	<i>250</i>
4	1 set	Reverse Camera <i>2nd</i>		380.00	<i>✓ 300.00</i>
5	1 set	Body Panel Joint Sealant <i>new</i>		120.00	<i>60</i>
6	1 pc	Rear Floor Panel Insulator Pad <i>new</i>		150.00	<i>+</i>
			<i>640</i>	subtotal	1,010.00

Labour charge

Panel Beating		1,800.00	<i>→ 1200</i>
Spray painting		1,800.00	<i>→ 900</i>
Check Wiring on tailamp		120.00	<i>30</i>
Anti rust		120.00	<i>80 100.</i>
Remove and install rear winscreen.		120.00	<i>✓</i>
Remove and install tailgate parts.		120.00	<i>80</i>
Remove and install interior uphoslttery		150.00	<i>80</i>
Remove and install reverse camera.		150.00	<i>50</i>
Remove and install reverse sensor		120.00	<i>50</i>
		Subtotal	\$ 4,500.00

2610

Total 17,191.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian Lij
2/s 17/12/24
kw of dya 09.
total: 1010523.28
2/s: 8.4K
(8.4K)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

 Owner ID Type:	Singapore NRIC
 Owner ID:	272H
 Feedback	SJW4000J
Vehicle to be Exported:	Yes
 Intended Deregistration Date:	28 Feb 2030
 Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	L15B3517018
Chassis No.:	RU11017007
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,307.00
Original Registration Date:	24 Mar 2015
First Registration Date:	24 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$8,307.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	28 Feb 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	5
PQP Paid:	\$47,257.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Jul 2025

OK