



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KIM SOON LEE PTE LTD
200 BEDOK SOUTH AVENUE 1
SINGAPORE 469331

Contact : 92472397 83258628

TP ECICS

Veron.

TAX INVOICE

Repair Code : CLM18492

Date in : 24/02/2025

Vehicle Num. : XE4820M

Model : SCANIA P370A4X2NZ

Chassis/Eng# : YS2P4X20005540348/DC13149L017148735

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH BUMPER SIDE <i>Dishled</i>	1	1650.00	1,650.00 <i>850</i>
FRONT LH BUMPER SIDE OUTER CHROME MOULDING <i>new</i>	1	327.30	327.30
FRONT LH CORNER GARNISH <i>new</i>	1	1936.00	1,936.00
FRONT LH DOOR ARCH GARNISH <i>new</i>	1	789.50	789.50
FRONT LH FOGLAMP <i>could</i>	1	795.00	795.00
FRONT LH HEADLAMP <i>cut</i>	1	6759.50	6,759.50
FRONT LH HEADLAMP OUTER GARNISH <i>could</i> <i>nn</i>	1	1750.00	1,750.00
FRONT LH STEP GARNISH <i>new</i>	1	881.70	881.70
FRONT LH STEP GARNISH LOWER GARNISH <i>could</i>	1	237.50	237.50
Subtotal before discount			15,126.50
Percentage discount 0%			0.00
Sub-total 1			15,126.50
FRONT LH BUMPER SIDE CLIPS - SET <i>new</i>	1	30.00	30.00
FRONT LH CORNER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00
FRONT LH DOOR ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00
FRONT LH HEADLAMP OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KIM SOON LEE PTE LTD
200 BEDOK SOUTH AVENUE 1
SINGAPORE 469331

Contact : 92472397 83258628

TAX INVOICE

Repair Code : CLM18492

Date in : 24/02/2025

Vehicle Num. : XE4820M

Model : SCANIA P370A4X2NZ

Chassis/Eng# : YS2P4X20005540348/DC13149L017148735

Subtotal before discount	120.00
Percentage discount 0%	0.00
Sub-total 2	120.00
Parts-total	15,246.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,380.00
Parts & Labour Total	16,626.50

580 30 80.00
350 600.00
200 600.00
+ 100.00

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants (Pte) Ltd
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

page 2

Adrian C
2/5 24/02/25

03Ryr

Total: 3066.05

H/S: 2.6K

2.6K