



TO : **AIG MOTOR CLAIMS DEPTS**  
 VEHICLE NO : **SNM679H**  
 MODEL : **BYD ATTO 3**  
 DATE OF ACCIDENT : **30.11.2024**  
 TIME OF ACCIDENT : **11:25 HOURS**

21	FRONT WHEEL HUP RH <i>Byd</i>	1	\$ 318.00	\$ 318.00	✓
22	FRONT LINKAGE RH <i>Not m</i>	1	\$ 85.00	\$ 85.00	+
23	FRONT DOOR RH <i>Deanted</i>	1	\$ 2,650.00	\$ 2,650.00	> 1171
24	FRONT DOOR OUTER MOULDING RH <i>New</i>	1	\$ 152.00	\$ 152.00	+
25	FRONT DOOR HINGE RH <i>New</i>	2	\$ 85.00	\$ 170.00	+
26	FRONT DOOR WEATHER STRIP RH <i>New</i>	1	\$ 125.00	\$ 125.00	+
27	FRONT DOOR LOWER PROTECTOR RH <i>ut</i>	1	\$ 260.00	\$ 260.00	-
28	FRONT DOOR GLASS CHANNEL RH <i>New</i>	1	\$ 164.80	\$ 164.80	+
29	FRONT DOOR INNER LOCK RH <i>Not m</i>	1	\$ 245.00	\$ 245.00	+
30	FRONT DOOR INNER TRIM BOARD RH <i>New</i>	1	\$ 951.20	\$ 951.20	+
31	FRONT DOOR REGULATOR RH <i>Not m</i>	1	\$ 385.00	\$ 385.00	+
32	FRONT DOOR POWER WINDOW MOTOR RH <i>New</i>	1	\$ 455.00	\$ 455.00	+
33	FRONT DOOR SPEAKER RH <i>New</i>	1	\$ 345.00	\$ 345.00	+
34	FRONT DOOR PILLAR RH (OUTER) <i>Not m</i>	1	\$ 1,245.00	\$ 1,245.00	+

S.N: 660 6041  
 543690

TOTA PRICE \$ 14,640.00  
 LESS 20% 10% \$ 2,928.00  
 SUB TOTAL PRICE \$ 11,712.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	30
2	FRONT BUMPER LOWER GARNISH CLIP (SET) <i>Not m</i>	1	\$ 60.00	\$ 60.00	+
3	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	+
4	CENTRE GRILLE CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	+
7	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
8	FRONT FENDER ARCED GARNISH CLIP RH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	30
9	FRONT DOOR SEALANT <i>Not m</i>		\$ 120.00	\$ 120.00	+
10	FRONT DOOR TRIM BOARD CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
13	FRONT TYRE RH <i>Not m</i>	1	\$ 300.00	\$ 300.00	+
12	BRAKE OIL <i>New</i>	1	\$ 80.00	\$ 80.00	+

TOTAL \$ 860.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SNM679H**  
 MODEL : **BYD ATTO 3**  
 DATE OF ACCIDENT : 30.11.2024  
 TIME OF ACCIDENT : 11:25 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	+
4	WIRING CHECK	\$ 120.00	30
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	200
6	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	+
7	FOUR WHEEL ALIGNMENT	\$ 120.00	80
8	RESET ABS LIGHT	\$ 350.00	+
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	120

1630

**TOTAL** \$ 7,220.00

TOTAL PARTS COST : \$ 860.00  
 TOTAL LABOUR COST : \$ 7,220.00  
 TOTAL REPAIR COST : \$ 8,080.00

Adrian C  
 H/S 17/12/24  
 27 Days

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

total: 780690  
 H/S: 6250