



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ASP AUTOMOTIVE PTE LTD
68 CIRCULAR ROAD #02-01
SINGAPORE 049422

Contact : 90612201 84855584

TAX INVOICE

Repair Code : CLM18494

Date in : 12/12/2024

Vehicle Num. : GBH8349B

Model : NISSAN NV200 1.5 MT

Chassis/Eng# : VSKYBAM20Z0172388/K9KE628D623004

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Reh d</i>	1	541.50	✓ 541.50
FRONT BUMPER REINFORCEMENT <i>new</i>	1	625.90	+ 625.90
FRONT BUMPER SIDE RETAINER L/R <i>ALL</i>	2	25.00	+ 50.00
FRONT BUMPER SPONGE <i>Cracked</i>	1	326.50	✓ 326.50
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	21.00	+ 21.00
FRONT GRILLE <i>new</i>	1	356.20	+ 356.20
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	64.90	+ 64.90
FRONT RH HEADLAMP <i>new</i>	1	489.90	+ 489.90
FRONT RH HEADLAMP LOWER OUTER GARNISH <i>Cracked</i>	1	320.00	✓ 320.00
Subtotal before discount			2,795.90
Percentage discount 10%			279.59
Sub-total 1			2,516.31
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT BUMPER NUMBER PLATE <i>new</i>	1	25.00	+ 25.00
FRONT BUMPER NUMBER PLATE HOLDER <i>new</i>	1	50.00	+ 50.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	+ 30.00
FRONT RH HEADLAMP LOWER OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	20 30.00

*** This is a computer-generated document which requires no signature.***

KKK Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ASP AUTOMOTIVE PTE LTD
68 CIRCULAR ROAD #02-01
SINGAPORE 049422

Contact : 90612201 84855584

TAX INVOICE

Repair Code : CLM18494

Date in : 12/12/2024

Vehicle Num. : GBH8349B

Model : NISSAN NV200 1.5 MT

Chassis/Eng# : VSKYBAM20Z0172388/K9KE628D623004

Subtotal before discount	185.00
Percentage discount 0%	0.00
Sub-total 2	185.00
Parts-total	2,701.31

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

✓ 80.00
✓ 400.00
✓ 500.00
✓ 80.00

Labour Total	1,060.00
Parts & Labour Total	3,761.31

*** This is a computer-generated document which requires no signature.***

page 2

Admin C
L/S 18/12/24
02 Rys.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be received and
is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: