

REF: CS/CTI24120224/Avh3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MVTo in ~~Vehicle~~ No: _____at ~~Work~~ / _____

of _____

Insured: **GBG 1420D**

Policy No: _____

Claim No: **SNM24D207026**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GBH8349B** Yr Regn: **2018/Oct.**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Nissan NV200** C.D. **1461**Colour: **Silver** A/C: Insured / Std / NI / NASp. Reading: **102888** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **VSKYBAM2020172388**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: **175/70R14.**R: **175/70R14.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Git.

Front

Rear

R/Bal. **06** mmR/Bal. **06** mmL/Bal. **06** mmL/Bal. **06** mmD.O.A. **12/12/2024**D.O.A. **18/12/24.**

Survey held at

N51.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/1/25 **TP claim.**

Adrian confirmed LS \$1100 (red 2661.31, 70%)

COE Expiry:

Estimate given during: Yes (✓)

1st Survey: No ()

MV: **87K**PV: **10.3K**Nett: **26.7K**

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **2**

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS \$1

Photos

Others

Report Format: _____

Reported by: _____



ASP-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

ASP AUTOMOTIVE PTE LTD
68 CIRCULAR ROAD #02-01
SINGAPORE 049422

Contact : 90612201 84855584

TAX INVOICE

Repair Code : CLM18494

Date in : 12/12/2024

Vehicle Num. : GBH8349B

Model : NISSAN NV200 1.5 MT

Chassis/Eng# : VSKYBAM20Z0172388/K9KE628D623004

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Reh d</i>	1	541.50	✓ 541.50
FRONT BUMPER REINFORCEMENT <i>new</i>	1	625.90	+ 625.90
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	25.00	+ 50.00
FRONT BUMPER SPONGE <i>new</i>	1	326.50	✓ 326.50
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	21.00	+ 21.00
FRONT GRILLE <i>new</i>	1	356.20	+ 356.20
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	64.90	+ 64.90
FRONT RH HEADLAMP <i>new</i>	1	489.90	+ 489.90
FRONT RH HEADLAMP LOWER OUTER GARNISH <i>new</i>	1	320.00	✓ 320.00
Subtotal before discount			2,795.90
Percentage discount 10%			279.59
Sub-total 1			2,516.31
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT BUMPER NUMBER PLATE <i>new</i>	1	25.00	+ 25.00
FRONT BUMPER NUMBER PLATE HOLDER <i>new</i>	1	50.00	+ 50.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	+ 30.00
FRONT RH HEADLAMP LOWER OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	20 30.00

*** This is a computer-generated document which requires no signature.***

ASP AUTOMOTIVE PTE LTD
Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ASP AUTOMOTIVE PTE LTD
68 CIRCULAR ROAD #02-01
SINGAPORE 049422

Contact : 90612201 84855584

TAX INVOICE

Repair Code : CLM18494

Date in : 12/12/2024

Vehicle Num. : GBH8349B

Model : NISSAN NV200 1.5 MT

Chassis/Eng# : VSKYBAM20Z0172388/K9KE628D623004

Subtotal before discount	185.00
Percentage discount 0%	0.00
Sub-total 2	185.00
Parts-total	2,701.31

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

80.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

400.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

500.00

To apply anti-rust chemical on repaired and replaced panel.

80.00

Labour Total

1,060.00

Parts & Labour Total

3,761.31

*** This is a computer-generated document which requires no signature.***

page 2

Admin Cg
L/S 18/12/24
02 Rys.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: