

REF: CS/AIG24120226/Avh3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: ~~Estim~~ \_\_\_\_\_OD / ~~TP~~ RES / CD RES / EVA / INV / MVTo in ~~Vehicle~~ No: \_\_\_\_\_at W ~~End~~ m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: 1900090610

Policy No: 2375862235SG

Claim's No: \_\_\_\_\_

Sum ~~INS~~ Excess: 1600

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLA3099Z Yr Regn: 2019, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.D. 1984

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 82850 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZF42KA050341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. 14/12/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 18/12/24

Premium

Date / Time Action / Instruction

19/2/25 Final fig \$6108 confirmed by email (Red 39,428, 86%)

COE Expiry

Estimate given during : Yes ( )

1st Survey : No ( )

MV: 87K

PV: 48.3K

Nett: 38.7K

Date/Time, File Pass to?

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Forward:

Report Forward:

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Inve (\$)

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0927/2024/EQ  
**DATE** : 17-Dec-24  
**WIP** : 42015

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/12/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR AW HOCK GUAN (HU FUYUAN)  
**ADDRESS** : BLK 2 TOH YI DRIVE  
#12-173  
SINGAPORE 590002

**TELEPHONE** : HP +65 98340858  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900090610-04  
**VEHICLE NO** : **SLA 3099 Z**  
**MODEL CODE** : AUDI A4 SEDAN 2.0 TFSI  
**MODEL YEAR** : 23/4/2019  
**ENGINE NO** : CVK 078401  
**CHASSIS NO** : WAUZZZF42KA050341  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 14-Dec-24  
**PLACE OF ACCIDENT** : LOR 22 GEYLANG, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 3099 Z**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	✗
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	✗
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$	3,200.00	✗
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS A-PILLAR. TO REMOVE AND REINSTALL RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	1000
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS A-PILLAR.	\$	3,300.00	2200
<b>SUBTOTAL LABOUR CHARGES</b>		: \$	<b>14,730.00</b>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 3099 Z**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW FRONT WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	680.00	X
8	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 16,102.00</b>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 3099 Z**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delud</i>	1	\$ 2,670.00	✓
2	FRONT BUMPER FIXING PARTS	1	\$ 648.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH <i>2</i>	2	\$ 90.00	+
4	FRONT BUMPER GRILLE - CENTER	1	\$ 245.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>2</i>	1	\$ 286.00	+
6	FRONT BUMPER AIR GUIDE - RH <i>new</i>	1	\$ 80.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 169.00	+
8	FRONT BUMPER TOP BRACKET <i>new</i>	1	\$ 173.00	+
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 156.00	+
10	FRONT BUMPER REINFORCEMENT BEAM <i>2</i>	1	\$ 1,033.00	+
11	FRONT BUMPER REINFORCEMENT BEAM SUPPORT - LH / RH <i>2</i>	2	\$ 73.00	+
12	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 30.00	+
13	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	1	\$ 286.00	+
14	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	+
15	HEADLIGHT - RH <i>2</i>	1	\$ 9,325.00	+
16	HEADLIGHT COMPENSATING PIECE <i>2</i>	3	\$ 150.00	+
17	LIFT CYLINDER - RH	1	\$ 252.00	?
18	LIFT CYLINDER BRACKET	1	\$ 8.00	?
19	LIFT CYLINDER HOSE <i>new</i>	1	\$ 118.00	+
20	FRONT FENDER - RH <i>Regis</i>	1	\$ 918.00	+
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 16,721.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 3099 Z**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
21	FRONT FENDER ATTACHMENT PARTS	1	\$ 241.00	+
22	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 90.00	+
23	FRONT FENDER BRACKET - RH FRONT	1	\$ 45.00	+
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 72.00	+
25	FRONT FENDER RIVET	6	\$ 26.00	+
26	FRONT FENDER BRACKET - RH REAR	1	\$ 67.00	+
27	FRONT FENDER BRACKET - RH UPPER	1	\$ 42.00	+
28	FRONT FENDER BRACE - RH	1	\$ 177.00	+
29	FRONT FENDER LEDGE COVER - RH OUTER	1	\$ 39.00	+
30	FRONT FENDER LEDGE COVER - RH FRONT	1	\$ 29.00	+
31	FRONT FENDER LEDGE COVER - RH INNER	1	\$ 76.00	+
32	BONNET	1	\$ 3,470.00	+
33	BONNET IMPACT PROTECTION - CENTER / RH / LH	3	\$ 107.00	+
34	BONNET ATTACHMENT PARTS	1	\$ 460.00	+
35	FRONT PILLAR A/B WITH FRAME MEMBER - RH	1	\$ 3,320.00	+
36	FRONT WINDOW GUIDE CHROME TRIM STRIP	1	\$ 320.00	+
37	FRONT WINDSCREEN	1	\$ 1,618.00	+
38	FRONT RAIN SENSOR GEL FOIL	1	\$ 140.00	+
39	PRIMER	1	\$ 27.00	+
40	FRONT DATA TAG	1	\$ 567.00	+
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 10,933.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 3099 Z**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	+
42	METAL FILTER POWDER	S/N	\$ 280.00	+
43	ACRYLIC SEALANT	S/N	\$ 180.00	+
44	STONE CHIP	S/N	\$ 180.00	+
45	CAVITY WAX	S/N	\$ 140.00	+
46	SUNDRIES		\$ 800.00	+
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 29,434.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 16,102.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 45,536.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Cj*  
SURVEYED DATE : *18/12/24*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT