

ASSIGNMENT

Others	1
--------	---

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0927/2024/EQ
DATE : 17-Dec-24
WIP : 42015

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR AW HOCK GUAN (HU FUYUAN)
ADDRESS : BLK 2 TOH YI DRIVE
#12-173
SINGAPORE 590002

TELEPHONE : HP +65 98340858
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900090610-04
VEHICLE NO : **SLA 3099 Z**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 23/4/2019
ENGINE NO : CVK 078401
CHASSIS NO : WAUZZZF42KA050341
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Dec-24
PLACE OF ACCIDENT : LOR 22 GEYLANG, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 3099 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	✗
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	✗
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$	3,200.00	✗
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS A-PILLAR. TO REMOVE AND REINSTALL RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	1000
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS A-PILLAR.	\$	3,300.00	2200
SUBTOTAL LABOUR CHARGES		: \$	14,730.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 3099 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW FRONT WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	680.00	X
8	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	X
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 16,102.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 3099 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delud</i>	1	\$ 2,670.00	✓
2	FRONT BUMPER FIXING PARTS	1	\$ 648.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH <i>2</i>	2	\$ 90.00	+
4	FRONT BUMPER GRILLE - CENTER	1	\$ 245.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>2</i>	1	\$ 286.00	+
6	FRONT BUMPER AIR GUIDE - RH <i>new</i>	1	\$ 80.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 169.00	+
8	FRONT BUMPER TOP BRACKET <i>new</i>	1	\$ 173.00	+
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 156.00	+
10	FRONT BUMPER REINFORCEMENT BEAM <i>2</i>	1	\$ 1,033.00	+
11	FRONT BUMPER REINFORCEMENT BEAM SUPPORT - LH / RH <i>2</i>	2	\$ 73.00	+
12	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 30.00	+
13	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	1	\$ 286.00	+
14	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	+
15	HEADLIGHT - RH <i>2</i>	1	\$ 9,325.00	+
16	HEADLIGHT COMPENSATING PIECE <i>2</i>	3	\$ 150.00	+
17	LIFT CYLINDER - RH	1	\$ 252.00	?
18	LIFT CYLINDER BRACKET	1	\$ 8.00	?
19	LIFT CYLINDER HOSE <i>new</i>	1	\$ 118.00	+
20	FRONT FENDER - RH <i>Regis</i>	1	\$ 918.00	+
SUB TOTAL SPARE PARTS		:	\$ 16,721.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 3099 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS	1	\$ 241.00	+
22	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 90.00	+
23	FRONT FENDER BRACKET - RH FRONT	1	\$ 45.00	+
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 72.00	+
25	FRONT FENDER RIVET	6	\$ 26.00	+
26	FRONT FENDER BRACKET - RH REAR	1	\$ 67.00	+
27	FRONT FENDER BRACKET - RH UPPER	1	\$ 42.00	+
28	FRONT FENDER BRACE - RH	1	\$ 177.00	+
29	FRONT FENDER LEDGE COVER - RH OUTER	1	\$ 39.00	+
30	FRONT FENDER LEDGE COVER - RH FRONT	1	\$ 29.00	+
31	FRONT FENDER LEDGE COVER - RH INNER	1	\$ 76.00	+
32	BONNET	1	\$ 3,470.00	+
33	BONNET IMPACT PROTECTION - CENTER / RH / LH	3	\$ 107.00	+
34	BONNET ATTACHMENT PARTS	1	\$ 460.00	+
35	FRONT PILLAR A/B WITH FRAME MEMBER - RH	1	\$ 3,320.00	+
36	FRONT WINDOW GUIDE CHROME TRIM STRIP	1	\$ 320.00	+
37	FRONT WINDSCREEN	1	\$ 1,618.00	+
38	FRONT RAIN SENSOR GEL FOIL	1	\$ 140.00	+
39	PRIMER	1	\$ 27.00	+
40	FRONT DATA TAG	1	\$ 567.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,933.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 3099 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	+
42	METAL FILTER POWDER	S/N	\$ 280.00	+
43	ACRYLIC SEALANT	S/N	\$ 180.00	+
44	STONE CHIP	S/N	\$ 180.00	+
45	CAVITY WAX	S/N	\$ 140.00	+
46	SUNDRIES		\$ 800.00	+
TOTAL SPARE PARTS		:	\$ 29,434.00	
TOTAL LABOUR CHARGES		:	\$ 16,102.00	
GRAND TOTAL		:	\$ 45,536.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Cj*
SURVEYED DATE : *18/12/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT