

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP China
Hui Rong

CS HOME CARPENTRY ART PTE LTD
469A YISHUN STREET 43 #10-23
SINGAPORE 761469

TAX INVOICE

Repair Code : CLM16322

Date in : 10/06/2024

Vehicle Num. : YQ5843R

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JHHAGV4620K001566/1GD8854675

Contact : 98619284

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Del'd</i>	1	895.20	✓ 895.20
FRONT BUMPER RH FOGLAMP GARNISH <i>new</i>	1	75.00	+ 75.00
FRONT BUMPER RH INNER BRACKET <i>new</i>	1	150.50	+ 150.50
FRONT RH CORNER PANEL <i>Rep's</i>	1	336.40	+ 336.40
FRONT RH DOOR <i>Del'd</i>	1	1794.20	1430 ✓ 1,794.20
FRONT RH DOOR GLASS CHANNEL <i>Best</i>	1	704.80	85 ✓ 704.80
FRONT RH DOOR GLASS CHANNEL RUBBER <i>new</i>	1	243.70	+ 243.70
FRONT RH DOOR GLASS OUTER MOULDING <i>ent</i>	1	113.60	✓ 113.60
FRONT RH DOOR GLASS REGULATOR <i>new</i>	1	355.40	+ 355.40
FRONT RH DOOR GLASS REGULATOR MOTOR <i>new</i>	1	355.90	+ 355.90
FRONT RH DOOR HINGE (LOWER) <i>new</i>	1	110.00	+ 110.00
FRONT RH DOOR HINGE (TOP)	1	110.00	+ 110.00
FRONT RH DOOR INNER RUBBER GUIDE STOPPER <i>new</i>	2	27.40	+ 54.80
FRONT RH DOOR INNER TRIM BOARD <i>Del'd</i>	1	858.90	690 ✓ 858.90
FRONT RH DOOR INNER TRIM BOARD MOULDING <i>new</i>	1	181.90	+ 181.90
FRONT RH DOOR LOCK STRIKER <i>new</i>	1	39.30	+ 39.30
FRONT RH DOOR MECHANISM LOCK <i>Del'd</i>	1	316.00	✓ 316.00
FRONT RH DOOR OUTER FRAME GARNISH <i>new</i>	1	80.10	+ 80.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

CS HOME CARPENTRY ART PTE LTD
 469A YISHUN STREET 43 #10-23
 SINGAPORE 761469

Contact : 98619284

TAX INVOICE

Repair Code : CLM16322

Date in : 10/06/2024

Vehicle Num. : YQ5843R

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JHHAGV4620K001566/1GD8854675

FRONT RH DOOR OUTER HANDLE <i>cut</i>	1	110.70	✓ 110.70
FRONT RH DOOR WEATHER STRIP <i>torn</i>	1	243.70	✓ 243.70
FRONT RH DOOR WEATHER STRIP ARCH <i>new</i>	1	186.80	+ 186.80
FRONT RH DOOR WEATHER STRIP VERTICAL <i>new</i>	1	115.30	+ 115.30
FRONT RH DOOR WINDOW GLASS <i>at</i>	1	692.70	✓ 692.70
FRONT RH HEADLAMP <i>new</i>	1	892.90	+ 892.90
FRONT RH PILLAR ARCH GARNISH <i>new</i>	1	270.90	+ 270.90
FRONT RH PILLAR ARCH RUBBER MOULDING <i>new</i>	1	110.70	✓ 110.70
FRONT RH PILLAR WEATHER STRIP <i>new</i>	1	170.20	+ 170.20
FRONT RH SEAT BELT <i>new</i>	1	896.90	✓ 896.90
FRONT RH STEP GARNISH <i>new</i>	1	302.80	+ 302.80
REAR CABIN FRONT HEADSTOCK <i>new repair</i>	1	1459.00	+ 1,459.00
REAR RH PILLAR INNER GARNISH <i>new</i>	1	376.90	+ 376.90
REAR RH PILLAR OUTER <i>Dented</i>	1	956.50	✓ 956.50
REAR RH SIDE RUBBER STOPPER <i>new cut</i>	1	65.00	✓ 65.00
REAR RH SIDE TAILGATE <i>Dented</i>	1	2985.00	2065 2,985.00
REAR RH TAILGATE SIDE LOCK <i>new</i>	1	279.70	✓ 279.70
REAR RH TAILGATE SIDE LOCK STRIKER <i>new</i>	1	155.10	+ 155.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

CS HOME CARPENTRY ART PTE LTD
 469A YISHUN STREET 43 #10-23
 SINGAPORE 761469

Contact : 98619284

TAX INVOICE

Repair Code : CLM16322

Date in : 10/06/2024

Vehicle Num. : YQ5843R

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JHHAGV4620K001566/1GD8854675

REAR RH TAILLAMP	Ne m	9054.10 S.N. 45	1	396.90	+	396.90
REAR RH TAILLAMP BRACKET	Ne m	679057	1	271.60	+	271.60
Subtotal before discount						17,715.00
Percentage discount 25%						4,428.75
Sub-total 1						13,286.25
CHASSIS NO STICKER	Nu		1	100.00	60	100.00
FRONT RH DOOR COMPANY STICKER	Nu		1	25.00	✓	25.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	Nu		1	40.00	30	40.00
REAR CANOPY CURTAIN	torn		1	900.00	300	900.00
REAR RH SIDE TAILGATE ALUMINIUM PLATE	Ne m	965	1	900.00	+	900.00
REAR RH SIDE TAILGATE ALUMINIUM PLATE RIVET - SET	Nu		1	100.00	50	100.00
REAR RH SIDE TAILGATE TOP STEEL BAR	Dented		1	1000.00	50	1,000.00
Subtotal before discount						3,065.00
Percentage discount 0%						0.00
Sub-total 2						3,065.00
Parts-total						16,351.25

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

30 ~~80.00~~

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

x 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

CS HOME CARPENTRY ART PTE LTD
469A YISHUN STREET 43 #10-23
SINGAPORE 761469

Contact : 98619284

TAX INVOICE

Repair Code : CLM16322

Date in : 10/06/2024

Vehicle Num. : YQ5843R

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JHHAGV4620K001566/1GD8854675

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 ~~100.00~~

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

40 ~~80.00~~

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

2190

1000 ~~1,800.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1000 ~~1,400.00~~

To apply anti-rust chemical on repaired and replaced panel.

60 ~~140.00~~

Labour Total

3,680.00

Parts & Labour Total

20,031.25

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin L;

h/s 11/06/24

07 days.

Total: 9990.57

h/s: 8k

8k