

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 28-Jun-24

Estimate no.

1416

Plate No. FBT6818P

Model. AEROX V1

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	450.00	✓	
2	FORK T-UNDER BRACKET	280.00	✓	
3	STEERING CONE	150.00	✓	
4	FRONT FENDER INNER COVER	120.00	✓	
5	FRONT SPORT RIM	400.00	✓	
6	FRONT TYRE SHAFT	100.00	✓	
7	HEAD LAMP	450.00	✓	
8	HEAD LAMP STAY	280.00	✓	
9	ABS PUMP	950.00	✓	
10	HANDLE BAR	280.00	✓	
11	MIRROR SET	120.00	✓	
12	FRONT FOOTREST BOARD R	150.00	✓	
13	FRONT FOOTREST BOARD L	150.00	✓	
14	FRONT FOOTREST UNDER COVER R	120.00	✓	
15	FRONT FOOTREST UNDER COVER L	120.00	✓	
16	INNER PANEL R	120.00	✓	
17	INNER PANEL L	120.00	✓	
18	FRONT SIGNAL R	150.00	✓	
19	FRONT SIGNAL L	150.00	✓	
20	BODY UNDER COVER	180.00	✓	
21	FUEL TANK INNER COVER	100.00	✓	
22	SIDE STAND	100.00	✓	
23	REAR FOOTREST L	180.00	✓	
24	AIR BOX COVER	150.00	✓	
25	MAINSTAND	180.00	✓	
26	REAR BOX	350.00	✓	
27	REAR BOX BRACKET	300.00	✓	

102

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 28-Jun-24

Estimate no. 1416

Plate No. FBT6818P

Model. AEROX V1

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
28	HEADLAMP UNDER COVER	80.00	✓	
29	BODY ALIGNMENT	800.00	300	
30	COVERSET	450.00	✓	
31	LABOUR	600.00	300	
32	FRONT FAIRING INNER COVER R	100.00	✓	
33	FRONT FAIRING INNER COVER L	100.00	✓	

102

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 833.00
 \$ 8,330.00
 Sub Total : \$ 7,497.00
 GST 9% \$ 674.73
 Total: \$ 8,171.73

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

P-4570
 102
 4113.00
 300
 680
 4093
 206
 4074.40