

(08/11/13) wef

REF:

CS/SMR 24070020/UVH3

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FB76818P

at Workshop m/s

Erret He

of

Insured:

SHB525M

Policy No.

Claims No. TAX/06/24/2054

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

\$13k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

194k

Vehicle: IN / OUT

Date:

Person Contacted:

L7A57264

Veh No:

FB76818P

Yr Regn:

22/04/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha zerox 155

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp.Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

No key

C/No:

MLESG584111050911

Gen. Cond: Good / Fair / Poor / Burnt

Steerings: Inorder / Jammed / Leaked / Burnt or

offhub

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

110-80-14

R:

140-70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/06/24

D.O.I.

2/7/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

RM, n/s Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

N/A \$5736

L/S \$4000

independ AH Kion

(red 3497, 46%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	194K
Vehicle Details	
Vehicle No.:	FBT6818P
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jul 2024
Vehicle Make:	YAMAHA
Vehicle Model:	AEROX 155A
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	G3M1E050910
Chassis No.:	MLESG584111050911
Maximum Power Output:	-
Open Market Value:	\$3,010.00
Original Registration Date:	22 Apr 2022
First Registration Date:	22 Apr 2022
Transfer Count:	1
Actual ARF Paid:	\$452.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Apr 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$9,310.00
COE Rebate Amount:	\$7,264.00
Total Rebate Amount:	\$7,264.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 02 Jul 2024

OK



Yamaha Aerox 155

Reg Date : 08/12/2020

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 45000km

SGD \$10800

Posted on : 25/05/2024

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 05/10/2020

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 35000km

SGD \$14800

Posted on : 26/05/2024

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 22/10/2020

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 56000km

SGD \$10800

Posted on : 11/05/2024

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 05/05/2022

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 25000km

SGD \$13888

Posted on : 27/04/2024

★ Paid Ad

★ Dealer Ad

Details >

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 28-Jun-24

Estimate no.

1416

Plate No. FBT6818P

Model. AEROX V1

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	450.00	✓	
2	FORK T-UNDER BRACKET	280.00	✓	
3	STEERING CONE	150.00	✓	
4	FRONT FENDER INNER COVER	120.00	✓	
5	FRONT SPORT RIM	400.00	✓	
6	FRONT TYRE SHAFT	100.00	✓	
7	HEAD LAMP	450.00	✓	
8	HEAD LAMP STAY	280.00	✓	
9	ABS PUMP	950.00	✓	
10	HANDLE BAR	280.00	✓	
11	MIRROR SET	120.00	✓	
12	FRONT FOOTREST BOARD R	150.00	✓	
13	FRONT FOOTREST BOARD L	150.00	✓	
14	FRONT FOOTREST UNDER COVER R	120.00	✓	
15	FRONT FOOTREST UNDER COVER L	120.00	✓	
16	INNER PANEL R	120.00	✓	
17	INNER PANEL L	120.00	✓	
18	FRONT SIGNAL R	150.00	✓	
19	FRONT SIGNAL L	150.00	✓	
20	BODY UNDER COVER	180.00	✓	
21	FUEL TANK INNER COVER	100.00	✓	
22	SIDE STAND	100.00	✓	
23	REAR FOOTREST L	180.00	✓	
24	AIR BOX COVER	150.00	✓	
25	MAINSTAND	180.00	✓	
26	REAR BOX	350.00	3005/2	
27	REAR BOX BRACKET	300.00	✓	

102

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 28-Jun-24

Estimate no. 1416

Plate No. FBT6818P

Model. AEROX V1

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
28	HEADLAMP UNDER COVER	80.00	✓	
29	BODY ALIGNMENT	800.00	300	
30	COVERSET	450.00	✓	
31	LABOUR	600.00	300	
32	FRONT FAIRING INNER COVER R	100.00	✓	
33	FRONT FAIRING INNER COVER L	100.00	✓	

102

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, etc. for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be raised and approved
- Final settlement is subject to final approval from Insurer's Surveyor

Acknowledged by Repairer:

Signature:

Date:

Less 10% \$ 833.00
 \$ 8,330.00
 Sub Total : \$ 7,497.00
 GST 9% \$ 674.73
 Total: \$ 8,171.73

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

p-4570
 102
 4113.00
 300
 080
 4093
 206
 407440