

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CS/AIG24120227/AQH3E2**Date:** 17/01/2025REFERENCE

Insured/Claimant:	THAM WAI LEONG	Policy No:	1800079954	
Date of Loss:	15/12/2024	Nature of Claim:	OD	Claim No: 4663412108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5466L		
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Engine No:	CYG023417
Reg. Date:	07/07/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ4GXJN039737
Colour:	White	Odometer:	157118 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,751.00	6,135.60	4,615.40	42.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,372.00	1,822.00	2,550.00	58.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,123.00	7,957.60	7,165.40	47.38
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	14,123.00	6,957.60	7,165.40	50.74
+ GST 9.00/9.00% (\$\$)	1,271.07	626.18	644.89	50.74
Nett Amount (\$\$)	15,394.07	7,583.78	7,810.29	50.74

INSPECTION

Date of Assignment:	18/12/2024		
Date Inspected:	18/12/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,903.00 FS	*3,122.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	608.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	61.00 FS	*- FS
4	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	117.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	160.00 FS	*- FS
6	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	48.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Torn	266.00 FS	*212.40 FS
8	1		*FRONT BUMPER SPOILER - LOWER	Not Necessary	310.00 FS	*- FS
9	1		*FRONT SPOILER	Repair	1,184.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cut	2,367.00 FS	*1,893.60 FS
11	1		*RADIATOR GRILLE COVER	Not Necessary	50.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	722.00 FS	*577.20 FS
13	1		*FRONT BUMPER CHANNEL COVER - RH	Not Necessary	65.00 FS	*- FS
14	1		*FRONT NUMBER PLATE	Cut	60.00 FS	*60.00 FS
15	1		*SUNDRIES	Necessary	500.00 FS	*6.40 FS
16	1		*RHS WHEEL HOUSING SPOILER	Torn	330.00 FS	*263.60 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,751.00	6,135.60
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			4,372.00	1,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >