

REF:

CS/ A14 24120227 / Aqhz

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / ~~TP~~ RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: 1000

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMC5466L Yr Regn: 2018 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Andi AB C.D. 1798Colour: White A/C: Insured / Std / NI / NASp. Reading: 157118 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU224GXJX039.737Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R17R: 225/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/12/24Survey held at PremiumDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

09. A1409/1/25 confirmed with Allan final fig \$ 7957.60, 3 days (Net \$ 7165.40, 472)

COE Expiry:

Estimate given during: Yes (✓)

1st Survey: No (✓)

MV: 78KPV: 45.8KNett: 32.2K

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Addl Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others

Report Format:

MER-00

Reported by: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0930/2024/EQ
DATE : 17-Dec-24
WIP : 42037

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR THAM WAI LEONG
ADDRESS : 317 TELOK KURAU ROAD
SINGAPORE 423865

TELEPHONE : HP +65 98318781
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800079954-06
VEHICLE NO : **SMC 5466 L**
MODEL CODE : AUDI A6 1.8 TFSI S TRONIC
MODEL YEAR : 7/7/2018
ENGINE NO : CYG 023417
CHASSIS NO : WAUZZZ4GXJN039737
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Dec-24
PLACE OF ACCIDENT : 53 SIMS PL, BLOCK 53, SINGAPORE 380053
BLOCK 53 SIMS PLACE CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 5466 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	500 ✓
3	TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER.	\$	2,000.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,372.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 5466 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
①	FRONT BUMPER <i>Defund</i>	1	\$ <i>3122.40</i> 3,903.00	✓ <i>St.S.</i>
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 608.00	+
3	FRONT BUMPER FIXING PARTS	1	\$ 61.00	+
4	FRONT BUMPER SECURING STRIP - LH / RH <i>3 new</i>	2	\$ 117.00	+
5	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 160.00	+
6	FRONT BUMPER ADAPTER - RH <i>new</i>	1	\$ 48.00	+
⑦	FRONT BUMPER CLOSING ELEMENT <i>tom</i>	1	\$ <i>212.40</i> 266.00	✓ <i>St.S.</i>
8	FRONT BUMPER SPOILER - LOWER <i>new</i>	1	\$ 310.00	+
9	FRONT SPOILER <i>Ryis</i>	1	\$ 1,184.00	+
10	RADIATOR GRILLE <i>ht</i>	1	\$ <i>1893.60</i> 2,367.00	✓
11	RADIATOR GRILLE COVER <i>new</i>	1	\$ 50.00	+
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>ht</i>	1	\$ <i>577.20</i> 722.00	✓
13	FRONT BUMPER CHANNEL COVER - RH <i>new</i>	1	\$ 65.00	+
14	FRONT NUMBER PLATE <i>ht</i>	S/N	\$ 60.00	✓
15	SUNDRIES <i>7 new</i>		\$ <i>6.40</i> 500.00	✓
TOTAL SPARE PARTS			: \$ 10,421.00	
TOTAL LABOUR CHARGES			: \$ 4,372.00	
GRAND TOTAL			: \$ 14,793.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Resurveyed
Admin G
St.S.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Xiao Chen.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0930/2024/EQ
24-Dec-24
JOON HONG
1 of 1
SMC 5466 L
AUDI A6 1.8 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
Parts			
1	RHS WHEEL HOUSING SPOILER <i>ton</i>	\$ 330.00	<i>✓ 263.60</i>
GRAND TOTAL		\$ 330.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling
H.S.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *18/12/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorised, 03849*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0930/2024/EQ
DATE : 17-Dec-24
WIP : 42037

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/12/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

3 Days - OK - Allan Boo

8-Jan-25

OWNER'S NAME : MR THAM WAI LEONG
ADDRESS : 317 TELOK KURAU ROAD
SINGAPORE 423865

TELEPHONE : HP +65 98318781
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800079954-06
VEHICLE NO : **SMC 5466 L**
MODEL CODE : AUDI A6 1.8 TFSI S TRONIC
MODEL YEAR : 7/7/2018
ENGINE NO : CYG 023417
CHASSIS NO : WAUZZZ4GXJN039737
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Dec-24
PLACE OF ACCIDENT : 53 SIMS PL, BLOCK 53, SINGAPORE 380053
BLOCK 53 SIMS PLACE CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 5466 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$	500.00
3	TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER.	\$	2,000.00	\$	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$	292.00
TOTAL LABOUR CHARGES		:	\$ 4,372.00	\$	1,822.00



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 5466 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,903.00	\$ 3,122.40
2	FRONT BUMPER FIXING PARTS	1	\$ 608.00	
3	FRONT BUMPER FIXING PARTS	1	\$ 61.00	
4	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 117.00	
5	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 160.00	
6	FRONT BUMPER ADAPTER - RH	1	\$ 48.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 266.00	\$ 212.40
8	FRONT BUMPER SPOILER - LOWER	1	\$ 310.00	
9	FRONT SPOILER	1	\$ 1,184.00	
10	RADIATOR GRILLE	1	\$ 2,367.00	\$ 1,893.60
11	RADIATOR GRILLE COVER	1	\$ 50.00	
12	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 722.00	\$ 577.20
13	FRONT BUMPER CHANNEL COVER - RH	1	\$ 65.00	
14	FRONT NUMBER PLATE	S/N	\$ 60.00	\$ 60.00
	ADD PARTS - SUPPLEMENTARY			\$ 263.60
15	SUNDRIES		\$ 500.00	\$ 6.40
TOTAL SPARE PARTS		:	\$ 10,421.00	\$ 6,135.60
TOTAL LABOUR CHARGES		:	\$ 4,372.00	\$ 1,822.00
GRAND TOTAL		:	\$ 14,793.00	\$ 7,957.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0930/2024/EQ 24-Dec-24 JOON HONG 1 of 1 SMC 5466 L AUDI A6 1.8 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	RHS WHEEL HOUSING SPOILER	\$ 330.00	\$ 263.60
GRAND TOTAL		\$ 330.00	\$ 263.60

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT