

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24120231/TQH3E2**Date:** 04/02/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMX7077C **Insured Vehicle No :** SNP2274M

Date of Loss: 29/11/2024 Nature of Claim: TP Claim No: DMPC2401659H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX7077C**

Make & Model: BMW X7, 3.0 (A) Engine No: 24525957B58B30C

Reg. Date: 17/09/2020 (Man. Year: 2020) Chassis No: WBACW220109C65090

Colour: White Odometer: 34255 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/45 R21 Rear Tyre Size: 285/45 R21

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,900.55	1,813.85	86.70	4.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	2,065.00	425.00	17.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,390.55	3,878.85	511.70	11.65
+ GST 9.00/9.00% (\$\$)	395.15	349.10	46.05	11.65
Nett Amount (\$\$)	4,785.70	4,227.95	557.75	11.65

INSPECTION

Date of Assignment: 16/12/2024

Date Inspected: 27/12/2024 Inspected At: Performance Motors Limited (HQ)
303 Alexandra Road, Singapore
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Feb 2025)	
Parts:	N/A	BMW X7 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX7077C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RH EXHAUST TAILPIPE TRIM	Cut	349.60 FS	*349.60 FS
3	1		*CHECK INNER REAR SUPPORT	Not Necessary	86.70 FS	*- FS
4	1		*REAR BUMPER RH PROTECTIVE RUBBER ST	Cut	156.70 FS	*156.70 FS
5	1		*REAR BUMPER COVER PAINTED	Cut	1,018.55 FS	*1,018.55 FS
6	20		*BLIND RIVET	Necessary	30.00 FS	*30.00 FS
7	17		*BLIND RIVET	Necessary	22.10 FS	*22.10 FS
8	1		*REAR BUMPER CENTRE MOUNT	Cracked	156.90 FS	*156.90 FS
Total Parts (S\$)					1,900.55	1,813.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER COVER PAINTED, MAKE GOOD PAINTWORKS, CHECK INNER SUPPORT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER AND AFFECTED AREAS	New	1,038.00	1,038.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	177.00
Gross Labour Cost (S\$)			2,490.00	2,065.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >