



Final Report

Estimate No. : **b1 71966**
Date Estimated : **29/11/2024**
Prepared By : **Yap Mee Key**

Page No. :

- **ESTIMATE REPAIR FOR** -
Huang ZhiJun
9 Sennett Lane

- **ACCOUNT** - **144674**
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

Singapore 466898

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMX7077C	WBACW220109C65090	17/09/2020	X7 xDrive40i	34647

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper cover, rear bumper RH protective strip, rear bumper centre mount, RH exhaust tailpipe trim include making good the rear bumper panel and carrying out other necessary repairs caused by the accident	850.00		850.00
To respray rear bumper	1,038.00		1,038.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET	1.50	20.00	0.00	30.00
# BLIND RIVET	1.30	17.00	0.00	22.10
RH EXHAUST TAILPIPE TRIM	349.60	1.00	0.00	349.60
# REAR BUMPER CENTRE MOUNT	156.90	1.00	0.00	156.90
REAR BUMPER RH PROTECTIVE RUBBER STRIP	156.70	1.00	0.00	156.70
REAR BUMPER COVER PAINTED	1,018.55	1.00	0.00	1,018.55

SUPPLEMENTARY ITEMS

Total Labour :	2,145.00
Total Parts :	1,733.85
Total Labour & Parts (before GST) :	3,878.85
Deduction for Excess :	
Total Repair Costs less Excess:	3,878.85
GST @9%:	349.10
Grand Total :	4,227.95

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W