

REF: C72/ CS/CTI24120232/Knh3e2 (SMQ 9692A)

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

DD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s L1mk

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1250

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: \$150K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 113.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMQ 9692A Yr Regn: 12 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Mw E200 Amb G.C 1991

Colour: M.D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 05214 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDP 2130422A 586109

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35ZR20

R: 275/30ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 7/12/24

Survey held at ✓

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S & o/s body

The UIC / ~~Chassis frame / Body~~ structure affected due to collision. ✓

Date / Time	Action / Instruction
<u>1</u>	<u>Midnight case, no modification.</u>
	<u>14/02/25 submit preli report-</u>
	<u>revised \$29011.55</u>
	<u>check items \$6663</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

\$ + RS. \$

Fuel

Others

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 & #07-03,
Sin Ming Autocity
575722

Insurer Reference: DMPCSNW00167082303
Repairer Reference: 74880
Date calculated: 17/12/2024 10:16 AM

Full Report
Registration: SMQ9692A
Printed: 17/12/2024 10:16 AM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSNW00167082303	Date of Incident:	07/12/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	MERCEDES-BENZ
Model:	E-CLASS (W213)
Sub Model:	E 200
Model Sheet Number:	03 FE 42
Registration:	SMQ9692A
VIN number:	WDD2130422A586109
Odometer:	

Model Specs

FROM A449969/L016369
HEADUNIT ECE/ROW
GARMIN MAP PILOT
ACTIVE BRAKE ASSIST
MEDIA DISPLAY 12,3"
HEATED FRONT SEATS
STORAGE PACKAGE
KEYLESS GO
CENTRE CONSOLE WOOD
AUTOMATIC 9-SPEED
8/9J X 20 ALU
INCR ANTI THEFT DEV
AMG STYLING
CLEAR COAT HARD

265/35-295/30 ZR20
AMG LINE
MODEL 2019
OUT/IN MIRR AUTO DIM
LED HEADLAMP
MULT FUNC ST/WHL LTH
ASH WOOD TRIM
ELECTRIC BOOTLID
PASS AIRBAG INTERRUPT
TYRE PRESSURE SENSOR
TYRE W/FLAT RUNNING
EMERGENCY CALL SYS
BODY SHELL LOAD LVL2

INSTR PANEL LEATHER
MOBILE COM-MODUL LTE
HEAT ABS GLAZING CPL
ELEC FOLD DR MIRRORS
ANTI-THEFT ALARM
MEMORY PACKAGE
PARK PILOT SYSTEM
ELECTRIC BOOTLID
SHIFT PADDLE ON STRG
AGILITY CONTR SUSPEN
EXTENDED FUEL TANK
PANORAMIC ROOF
TWO COAT METALLIC

AMG LINE
PREP MAP PILOT
MIRROR PACKAGE
REARVIEW CAMERA
PAD ARTICO MICROFIBR
INTERIOR PROTECTION
ANALOG CLOCK
RADIATOR SHROUD
DYNAMIC SELECT
PART-FILT WITH SENSR
PEDESTRIAN PROTECT
DAB TUNER
PREPARE OFF VEHICLE

Not Authorized
Repair By pain
£2 @ 1250f
14 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	12.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 7
Approved by Repairer
Signature:
Date:

PRINT DATE 17/12/2024

Insurer Reference: DMPCSNW00167082303
Repairer Reference: 74880
Date calculated: 17/12/2024 10:16 AM

Full Report
Registration: SMQ9692A
Printed: 17/12/2024 10:16 AM

Code	Description	WU	Price SGD
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	3.0	12.60
54-0650 01	MAIN BOARD MAINTAINED (FOR CHECK AND DIAGNOSIS WORK)	1.0	4.20
61-1087 01	R + R CENTRE AND REAR ENGINE COMPARTMENT COVERING	3.0	12.60
61-1088 01	R + R FRONT AND CENTRE ENGINE COMPARTMENT COVERING	4.0	16.80
61-1116 01	R + R L/UNDERFLOOR COVER	3.0	12.60
88-2532 01	REPAIR OF FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WINGS AND FRONT LAMP UNITS, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	44.0	184.80
88-1164 01	ADDITION FOR RENEW FRONT BUMPER (VEHICLE WITH ACTIVE BRAKE ASSIST)	1.0	4.20
88-1375 01	ADDITION TO RENEW FRONT BUMPER (VEHICLE WITH PEDESTRIAN PROTECT)	1.0	4.20
88-1376 01	ADD TO RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	3.0	12.60
82-4886 01	ADDITIONAL TO RENEW HEADLAMP (VEHICLE WITH LED HEADLAMP)	3.0	12.60
88-4668 01	R + R L/F WHEELARCH SHELL	4.0	16.80
88-4693 01	R + R R/F WHEELARCH SHELL	4.0	16.80
88-2657 01	R + R BOTH BONNET HINGE	4.0	16.80
91-2173 01	R + R L/BONNET STAY	3.0	12.60
91-2174 01	R + R R/BONNET STAY	3.0	12.60
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION	15.0	63.00
62-1266 01	R + R OR RENEW FRONT CROSSMEMBER AND COMPLETE TRUSSING BETWEEN WHEELHOUSES INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY	15.0	63.00
88-8802 01	REMOVE + REFIT REAR BUMPER INCLUDES: R + R CENTRE REAR PANEL TRIM AND TAILLAMP	13.0	54.60
88-8805 01	DIS + ASS REAR BUMPER (REMOVED)	7.0	29.40
88-8887 01	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	8.40
88-8890 01	ADDITION TO REAR BUMPER DIS + ASS (VEHICLE WITH TAILGATE OPENER)	1.0	4.20
20-3865 01)	R + R RADIATOR	7.0	29.40
09-6935 03)	R + R LOW-TEMPERATURE COOLER (ADD)	3.0	12.60
83-6543 01	R + R AIR CONDITIONING CONDENSER	14.0	58.80
27-7031 01	R + R OIL PAN AUTOMATIC GEARBOX	5.0	21.00
40-1590 01	R + R FRONT WHEELS	3.0	12.60
40-1470 01	ADD TO L/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH)	1.0	4.20
40-1470 01	ADD TO R/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH)	1.0	4.20
33-3620 01	R + R FRONT STEERING KNUCKLE	30.0	126.00

Surer Reference: DMPCSNW00167082303

Repairer Reference: 74880

Date calculated: 17/12/2024 10:16 AM

Full Report

Registration: SMQ9692A

Printed: 17/12/2024 10:16 AM

Code	Description	WU	Price SGD
33-1438 01)	DETACH + REFIT L/F TENSION ROD	4.0	16.80
33-1440 01)	DETACH + REFIT R/F TENSION ROD	4.0	16.80
33-1438 01)	R + R LEFT FRONT TORSION BAR	4.0	16.80
33-1440 01)	R + R RIGHT FRONT TORSION BAR	4.0	16.80
32-1955 01)	R + R L/F STRUT	6.0	25.20
32-1960 01)	R + R R/F STRUT	6.0	25.20
32-1965 01)	R + R FRONT SUSPENSION STRUT (ADD/WORK)	3.0	12.60
32-1908 01)	DISS/ASS L/F SUSPENSION STRUT REMOVED	3.0	12.60
32-1914 01)	DISS/ASS R/F SUSPENSION STRUT	3.0	12.60
32-1920 01)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	2.0	8.40
42-2724 01)	R + R L/F BRAKE CALIPER	3.0	12.60
42-2725 01)	R + R FRONT BRAKE CALIPER ASS WORK	3.0	12.60
33-1412 01)	R+R F/SPRING HANDLEBAR	2.0	8.40
40-2410 01	R + R LEFT FRONT TYRE	3.0	12.60
40-2410 01	R + R RIGHT FRONT TYRE	3.0	12.60
40-2410 01	R + R RIGHT REAR TYRE	3.0	12.60
40-2055 01	L/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	R/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	BALANCE R/R WHEEL	2.0	8.40
40-1580 01)	R + R REAR WHEEL ADD	1.0	4.20
40-2713 01	ADD TO WHEEL RENEW	3.0	12.60
	(VEHICLE WITH TYRE PRESSURE CHECK)		
40-1470 01	ADD TO R/R WHEEL REMOVE AND REFIT	1.0	4.20
	(ASSEMBLY ON WHEELS FROM 17 INCH		
49-5507 02	R + R CATALYST	11.0	46.20
49-5500 02)	RENEW CATALYST	3.0	12.60
42-1350 01	BLEED BRAKE SYSTEM	11.0	46.20
20-1190 01	ADDITION TO COOLING SYSTEM DRAIN /REFILL	3.0	12.60
	(VEHICLE WITH SEPARATE LOW TEMPERATURE-		
	WATER CYCLE)		
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID,	6.0	25.20
	EXHAUST, REFILL, PRESSURE TEST		
	(FOR ALL WORK ON THE SYSTEM)		
83-0640 01	CHECK AIR COND	1.0	4.20
82-1120 01	ADJUST HEADLAMPS	7.0	29.40
	(VEHICLE WITH LED HEADLAMP)		
	INCLUDES: ZERO POSITION FOR LED HEADLAMP		
	WITH STAR-DIAGNOSIS ADJUST		
40-6500 01	ALIGN VEHICLE	8.0	33.60
	INCLUDES: ALIGN FRONT AND REAR TOE AND		
	CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
1482	RIGHT FRONT DOOR REPAIR	15 20.0* ✓	84.00
1782	R/R DOOR REPAIR	15 20.0* ✓	84.00
2086	RIGHT DOOR FRAME REPAIR	25 30.0*	126.00
3482	R/R WING REPAIR	15 20.0*	84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		40.30	403.0
Alignment			
Measuring Work		0.80	8.0
Total of Labour			1,726.20

Surfer Reference: DMPCSNW00167082303
Repairer Reference: 74880
Date calculated: 17/12/2024 10:16 AM

Full Report
Registration: SMQ9692A
Printed: 17/12/2024 10:16 AM

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	31.0
	L/BONNET HINGE SURFACE PAINT	4.0
	R/BONNET HINGE SURFACE PAINT	4.0
	L/F WING NEW PART PAINTING	11.0
	R/F WING NEW PART PAINTING	11.0
	FRONT BUMPER TRIM NEW PART PAINT K1R	10.0
	R/SILL PANELLING NEW PART PAINT K1R	7.0
	REAR BUMPER COVER NEW PART PAINT K1R	12.0
	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0
	R/R DOOR REPAIR PAINTING <50%	15.0
	RIGHT DOOR FRAME REPAIR PAINTING <50%	7.0
	R/F SILL REPAIR PAINTING <50%	10.0
	R/LWR A-PILLAR REPAIR PAINTING <50%	8.0
	RIGHT B-PILLAR REPAIR PAINTING <50%	10.0
	R/R WING REPAIR PAINTING <50%	15.0

Paint Material Per Part

Code	Description	Price SGD
		107.33
0471	BONNET NEW PART PAINTING	0.25
0475	L/BONNET HINGE SURFACE PAINT	0.25
0476	R/BONNET HINGE SURFACE PAINT	22.70
0741	L/F WING NEW PART PAINTING	22.70
0742	R/F WING NEW PART PAINTING	47.23
0283	FRONT BUMPER TRIM NEW PART PAINT K1R	28.04
2208	R/SILL PANELLING NEW PART PAINT K1R	60.02
2583	REAR BUMPER COVER NEW PART PAINT K1R	30.04
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	25.19
1782	R/R DOOR REPAIR PAINTING <50%	2.91
2086	RIGHT DOOR FRAME REPAIR PAINTING <50%	11.31
2112	R/F SILL REPAIR PAINTING <50%	4.52
2240	R/LWR A-PILLAR REPAIR PAINTING <50%	11.31
2292	RIGHT B-PILLAR REPAIR PAINTING <50%	24.55
3482	R/R WING REPAIR PAINTING <50%	

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor		172.0	
Time Paint	2.50	25.0	105.00
Preparation Main Work Metal	0.50	5.0	21.00
Preparation Comp. Work Plastic			
Total	10 WU/h	202.0	848.40

Insurer Reference: DMPCSNW00167082303
 Repairer Reference: 74880
 Date calculated: 17/12/2024 10:16 AM

Full Report
 Registration: SMQ9692A
 Printed: 17/12/2024 10:16 AM

Material Cost - Paint

New Part Painting
 New Part Painting - Plastic K1R
 Repair Painting
 Surface-/Blend Paint
 Material-constant Metal Preparation
 Material-constant Plastic
Total

Price SGD
 152.73
 135.29
 109.83
 0.50
 28.60
 9.00
 435.95

Spare Parts

prices as at 2015-06-01
 Price SGD

Code	Description	Part Number	Part Source	
4465	AIR CON CONDENSER	099 500 0454	Original	Br/Pu ✓ 816.00
1007	ATF	6 LITRESG	Original	M ✓ 120.00
0471	BONNET	213 880 0357	Original	Br ✓ 1,295.00
8819	CATALYST	274 140 1708	Original	? 1,657.00
9987	COOLANT/ANTIFREEZE	NO NUMBER	Original	M ✓ 19.00
0390	CTR FRT BUMPER MLDG	213 885 7000	Original	Dr ✓ 260.00
8780	CTR LWR ENGINE CVR	213 524 2700	Original	CM ✓ 120.00
7789	FAN UNIT	099 906 1800	Original	? 950.00
0283	FRONT BUMPER TRIM	213 885	Original	Ta ✓ 1,220.00
		2700649999		
0930	FRONT MODULE CPL	213 620 6300	Original	mi ✓ 568.00
0257	FRONT NUMBER PLATE	KNPL3	Original	R ✓ 0.00
0349	FRT/CTR IMPACT DAMP	213 885 0103	Original	mi ✓ 105.00
1006	FRT BUMPER TRI-GRIP	RIVETX20	Original	mi ✓ 100.00
0377	FRT BUMPER W/	213 540 5403	Original	? 283.00
	HARNESS			
0305	FRT CT BUMP GRILLE	213 885 6900	Original	mi ✓ 120.00
0335	FRT CTR BUMPER CARR	213 885 2500	Original	R ✓ 100.00
8779	FRT ENGINE COVER	213 520 0900	Original	Bo ✓ 173.00
1001	FRT LWR CROSSMEMBER	213 620 0130	Original	Br ✓ 305.00
0260	FRT NO PLATE BRKT	213 880 2400	Original	mi ✓ 89.00
0491	FRT PRESSURE SENSOR	213 905 0914	Original	? 108.00
8896	GEARBOX OIL TUBE	725 271 2101		? 0.00
8891	GEARBOX SUMP	725 270 3707	Original	? 255.00
8897	GEARBOX WATER PIPE	725 271 6100		? 0.00
0405	GRILLE	213 888 0123 64	Original	CM ✓ 120.00
0477	L/BONNET ACTUATOR	213 906 2201	Original	Act ✓ 120.00
0475	L/BONNET HINGE	213 880 0128	Original	Dr ✓ 148.00
2621	L/BUMPER MNTG REINF	213 885 4905	Original	M ✓ 20.00
7155	L/F BRAKE CALIPER	011 421 9798	Original	? 1,083.00
0343	L/F BUMPER CARRIER	213 885 2300	Original	R ✓ 64.00
0303	L/F BUMP LWR GRILLE	213 885 6700	Original	CM ✓ 66.00
7071	L/F CONTROL ARM	205 330 6510	Original	R ✓ 353.00
0365	L/F INNER SENSOR	000 905 5504 9999	Original	? 100.00
0359	L/F INN SPACER RING	000 542 1251	Original	M ✓ 6.00
4283	L/FLOOR COVER	213 680 6307	Original	CM ✓ 168.00
0355	L/F OUT SPACER RING	000 542 1251	Original	M ✓ 6.00
7087	L/FR SHOCK ABSORBER	213 320 3630	Original	R ✓ 490.00
7201	L/FR WHEEL	213 401 2200 7X21	Original	Dr ✓ 1,395.00
7081	L/F STEERING KNUCKLE	213 332 4700	Original	Br ✓ 1,030.00
1189	L/F STRUT	253 620 1600	Original	R ✓ 45.00
7091	L/F STRUT BEARING	253 323 0020	Original	M ✓ 190.00
7047	L/F TENSION ROD	205 330 1305	Original	? 328.00
7061	L/F TRACK CONT ARM	205 330 5501	Original	Br ✓ 438.00

Insurer Reference: DMPCSNW00167082303
 Repairer Reference: 74880
 Date calculated: 17/12/2024 10:16 AM

Full Report
 Registration: SMQ9692A
 Printed: 17/12/2024 10:16 AM

Code	Description	Part Number	Part Source	Price SGD
1191	L/F UPP BUMP FRT ABS	213 620 1500	Original	155.00
7131	L/F WHEEL HUB	205 334 0400	Original	315.00
0839	L/F W-HOUSE FRT CVR	238 690 1503	Original	90.00
0841	L/F W-HOUSE RR COVER	238 691 1700	Original	155.00
0741	L/F WING	213 880 0118	Original	575.00
9649	L/H-LAMP LVL C-UNIT	213 900 2616	Original	415.00
9645	L/HORN	213 542 4400	Original	120.00
8767	L/LWR COVER BRACKET	213 524 0340	Original	24.00
0413	L/LWR GRILLE MLDG	213 888 0373 64	Original	48.00
7099	L/UPPER DAMPER RING	205 322 0184	Original	48.00
0411	L/UPP GRILLE MLDG	213 888 0173 64	Original	1,900.00
0561	LEFT HEADLAMP ASSY	213 906 6701	Original	545.00
7762	LOW TEMP RADIATOR	099 500 2003	Original	120.00
0478	R/BONNET ACTUATOR	213 906 2201	Original	148.00
0476	R/BONNET HINGE	213 880 0228	Original	20.00
2622	R/BUMPER MNTG REINF	213 885 5005	Original	64.00
0344	R/F BUMPER CARRIER	213 885 2400	Original	74.00
0304	R/F BUMP LWR GRILLE	213 885 6800	Original	353.00
7072	R/F CONTROL ARM	205 330 6610	Original	100.00
0366	R/F INNER SENSOR	000 905 5504 9999	Original	6.00
0360	R/F INN SPACER RING	000 542 1251	Original	6.00
0356	R/F OUT SPACER RING	000 542 1251	Original	490.00
7088	R/FR SHOCK ABSORBER	213 320 3630	Original	1,395.00
7202	R/FR WHEEL	213 401 2200 7X21	Original	950.00
7082	R/F STEERING KNUCKLE	213 332 4800	Original	190.00
7092	R/F STRUT BEARING	253 323 0020	Original	328.00
7048	R/F TENSION ROD	205 330 1405	Original	470.00
7062	R/F TRACK CONT ARM	205 330 5601	Original	315.00
7132	R/F WHEEL HUB	205 334 0400	Original	90.00
0840	R/F W-HOUSE FRT CVR	238 690 1603	Original	110.00
0842	R/F W-HOUSE RR COVER	238 691 1000	Original	575.00
0742	R/F WING	213 880 0018	Original	24.00
8768	R/LWR COVER BRACKET	213 524 0440	Original	1,483.00
9552	R/RR WHEEL	213 401 2300 7X21	Original	765.00
2208	R/SILL PANELLING	213 698 0600 9999	Original	48.00
7100	R/UPPER DAMPER RING	205 322 0184	Original	160.00
0437	RAD GRILLE COVER	213 888 0160 9982	Original	145.00
0407	RAD GRILLE FRAME	213 885 0200 64	Original	648.00
7761	RADIATOR	099 500 7303	Original	983.00
2583	REAR BUMPER COVER	213 885	Original	
		0801649999		
0562	RIGHT HEADLAMP ASSY	213 906 6801	Original	1,900.00
2627	RR LWR BUMPER COVER	213 885 1801	Original	248.00
0791	SCREW	001 990 6736	Original	50.00
0935	UPP FRT PANEL COVER	213 620 1701	Original	165.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings
Subtotal
Fixed Sundry Parts Price

Total

0.00
 31,694.00
 100.00
 31,794.00

Extras

Code	Description	Price SGD
1000	AIRCON GAS	50.00*

Insurer Reference: DMPCSNW00167082303
Repairer Reference: 74880
Date calculated: 17/12/2024 10:16 AM

Full Report
Registration: SMQ9692A
Printed: 17/12/2024 10:16 AM

Code	Description	Price SGD
1001	COMPUTERISED WHEEL ALIGNMENT	✓ 60.00*
1002	CHK/ERASE FAULT CODE AFTER REPAIR	✓ 120.00*
1003	REPROGRAM SRS CONTROL UNIT	7 350.00*
1004	REPROGRAM L/HEADLAMP LIGHT CONTROL	250 350.00*
1005	FRONT NUMBER PLATE	✓ 40.00*
Total Extras		970.00

Final Calculation

	SGD	SGD
Parts	31,694.00	
Fixed Sundry Parts Price	100.00	
Total Parts		31,794.00
Labour Time Base 10 WU/h	1,692.60	
Total 403.0 WU X 42.00 SGD/h		
Alignment	33.60	
Measuring Work		
Total of Labour		1,726.20
Total Of Extras		970.00
Paint Work Time Base 10 WU/h	848.40	
Labour Cost 202.0 WU X 42.00 SGD/h	435.95	
Material Cost		
Total Paint Including Material		1,284.35
Repair Cost Excludes GST		35,774.55
GST (+9.00%)		3,219.71
Repair Cost Included GST		38,994.26

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Your NCD will be affected due to late reporting

SLOM24CC0003-01 / Lai Huat (Meng Kee) Motor Pte Ltd
ENTRY DATE & TIME: 12/12/2024 16:43 (SGT)
SUBMITTED BY: Jenny Lim
VERSION: 2 (13/12/2024 14:10 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	12/12/2024 16:43 (SGT)
Reported by	Actual Driver
Date of Accident	07/12/2024 05:30 (SGT)
Exact Location of Accident	Temasek Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMQ9692A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Tan Thiam Heng
NRIC No	SXXXX627A
Email Address	kingsley.tkr@gmail.com
Mobile Phone No	(Phone) +65-96230655
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1991
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00167082303

DRIVER


SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
13 DEC 2024


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC card) **Jenny Lim**

Sketch Plan

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 12 Dec 2024

Singapore NRIC

627A

SMQ9692A

Yes

12 Dec 2024

MERCEDES BENZ

E200 AMG LINE AUTO

Blue

2018

27492031716475

WDD2130422A586109

135.0 kW (181 bhp)

\$56,449.00

12 Dec 2019

12 Dec 2019

0

\$73,609.00

Yes

11 Dec 2029

\$51,526.00

11 Dec 2029

B - Car above 1600cc or 97kW (130bhp)

10

\$40,009.00

\$19,989.00

\$71,515.00

OK