

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TRINC
Hui Rong

YVONNA CHAN YI JIE
BLK 685B JURONG WEST ST 64 #08-169
SINGAPORE 642685

TAX INVOICE

Repair Code : CLM16516

Date in : 16/12/2024

Vehicle Num. : SJV9561D

Model : TOYOTA VOXY 2.0X A

Chassis/Eng# : ZRR700286175/3ZRA451934

Contact : 98286046 96886383

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	2162.60	2162.60 1150
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	111.80	x 223.60
REAR END PANEL <i>Dented</i>	1	1151.30	1151.30 815
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	484.40	484.40 320
REAR FLOOR PANEL TOP BOARD COVER <i>new</i>	1	2093.20	x 2,093.20
REAR TAILGATE <i>Dented</i>	1	2930.00	2,930.00 1990
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	73.50	✓ 73.50
REAR TAILGATE 'VOXY' EMBLEM	1	79.60	✓ 79.60
REAR TAILGATE DAMPER L/R <i>new</i>	2	420.20	x 840.40
REAR TAILGATE HINGES L/R <i>new</i>	2	99.40	x 198.80
REAR TAILGATE INNER PULL HANDLE <i>new</i>	1	35.60	x 35.60
REAR TAILGATE INNER TRIM BOARD <i>Dented</i>	1	870.90	2 870.90 740
REAR TAILGATE LOCK STICKER <i>new</i>	1	56.70	x 56.70
REAR TAILGATE MECHANISM LOCK <i>Dented</i>	1	628.80	✓ 628.80
REAR TAILGATE NUMBER PLATE LAMP L/R <i>new</i>	2	70.00	x 140.00
REAR TAILGATE OUTER HANDLE <i>Dented</i>	1	179.50	✓ 179.50
REAR TAILGATE WEATHER STRIP <i>new</i>	1	515.40	380 515.40
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	327.00	✓ 327.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

YVONNA CHAN YI JIE
 BLK 685B JURONG WEST ST 64 #08-169
 SINGAPORE 642685

Contact : 98286046 96886383

TAX INVOICE

Repair Code : CLM16516

Date in : 16/12/2024

Vehicle Num. : SJV9561D

Model : TOYOTA VOXY 2.0X A

Chassis/Eng# : ZRR700286175/3ZRA451934

REAR TAILGATE WIPER ARM	<i>2 new</i>	1	128.30	<i>+</i>	128.30
REAR TAILGATE WIPER ARM COVER		1	31.30	<i>+</i>	31.30
REAR TAILGATE WIPER MOTOR	<i>2 new</i>	1	1143.50	<i>880</i>	1,143.50
REAR TAILLAMP L/R	<i>2 new</i>	2	771.40	<i>+</i>	1,542.80
Subtotal before discount					15,837.20
Percentage discount 25%					3,959.30
Sub-total 1					11,877.90
REAR BUMPER CLIPS - SET	<i>new</i>	1	80.00	<i>30</i>	80.00
REAR BUMPER LOWER SPOILER	<i>2 new</i>	1	1000.00	<i>680</i>	1,000.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>new</i>	1	50.00	<i>20</i>	50.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE ^{upper} LOWER SPOILER	<i>new</i>	1	1000.00	<i>+</i>	1,000.00
REAR TAILGATE NUMBER PLATE	<i>new</i>	1	25.00	<i>+</i>	25.00
REAR TAILGATE NUMBER PLATE HOLDER	<i>new</i>	1	50.00	<i>+</i>	50.00
REAR TAILGATE OUTER HANDLE CLIPS - SET	<i>new</i>	1	40.00	<i>20</i>	40.00
REAR TAILGATE OUTER RUBBER SEAL	<i>new</i>	1	100.00	<i>+</i>	100.00
REAR ^{Bumper} TAILGATE REVERSE SENSOR	<i>2 new</i>	1	350.00	<i>200</i>	350.00
REAR TAILGATE STICKER - SET	<i>new</i>	1	300.00	<i>180</i>	300.00

*** This is a computer-generated document which requires no signature.***

page 2

Rear tailgate reverse camera
2 new

SN A 600.00
380 (SN)

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

YVONNA CHAN YI JIE
BLK 685B JURONG WEST ST 64 #08-169
SINGAPORE 642685

Contact : 98286046 96886383

TAX INVOICE

Repair Code : CLM16516
Date in : 16/12/2024
Vehicle Num. : SJV9561D
Model : TOYOTA VOXY 2.0X A
Chassis/Eng# : ZRR700286175/3ZRA451934

REAR TAILGATE WINDSCREEN SEALANT <i>nee</i>	1	80.00	<i>60</i>	80.00
Subtotal before discount		<i>1510</i>		3,125.00
Percentage discount 0%				0.00
Sub-total 2				3,125.00
Parts-total				15,002.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.			<i>✓</i>	80.00
To remove, reinstall tailgate windscreen			<i>120</i>	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)			<i>60</i>	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		<i>1580</i>	<i>600</i>	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.			<i>600</i>	1,000.00
To apply anti-rust chemical on repaired and replaced panel.			<i>60</i>	120.00
To remove, reinstall tailgate mechanism and check for function			<i>60</i>	80.00
Labour Total				2,530.00
Parts & Labour Total				17,532.90

*** This is a computer-generated document which requires no signature.***

page 3
LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin LG
1/s 17/12/24
x/10 of days 0.6
total: 8557.42
4/s: 6.8K ✓