

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24070021/ENH3E2
Date: 18/07/2024**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MPC0006454
Claimant Vehicle No :	SBS6042R	Insured Vehicle No :	SGT1485P
Date of Loss:	20/06/2024	Nature of Claim:	TP
		Claim No:	MPC2024D0007511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6042R	Engine No:	90292609015931
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Chassis No:	WEB62808323121979
Reg. Date:	08/07/2011 (Man. Year: 2011)	Odometer:	734163 km
Colour:	Multi-colour		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5(D)
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	668.00	668.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	668.00	668.00	0.00	0.00
+ GST 9.00/9.00% (\$\$)	60.12	60.12	0.00	0.00
Nett Amount (\$\$)	728.12	728.12	0.00	0.00

INSPECTION

Date of Assignment:	01/07/2024	
Date Inspected:	01/07/2024	Inspected At: Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	1.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Jul 2024)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6042R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WORKSHOP LABOUR	New	188.00	188.00
2	CONTRACTORS REPAIR CHARGES	New	480.00	480.00
3	TOWING CHARGES (NPA)	New	0.00	0.00
Gross Labour Cost (\$)			668.00	668.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >