



HxGN EAM

Accident Report

User

ARIFMS@SBSTRANSIT.COM.SG

Report Created

Jul 2, 2024

EAM

Accident Report



Certificate of Bus Repair

Depot BN
Driver 81960
Work Order No 1371037

Bus No SBS6042R
Accident Date Jun 20, 2024
Case No / AR No 21105 / AR-2024-3434

Date IN Jul 1, 2024

Date Out

Jul 1, 2024

Registration Date	Model/Manufacturer	Chassis No.
Jul 8, 2011	MB Citaro O530, SD, AC, 2 Axle	WEB62808323121979

Stock Code	Description	Quantity	Total Material Cost (S\$)
------------	-------------	----------	---------------------------

Stock items not used in Work Order

TOTAL FOR PARTS		S\$	0.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	Workshop Labour	S\$	188.00
2	Contractor's Repair Charges	S\$	480.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$	668.00
Repair cost of Advertisement / Livery		S\$	0.00
TOTAL DAMAGE		S\$	668.00
Overheads		S\$	200.40
Towing Charges		S\$	0.00
Repair Period : 1.00 Days	Loss of Use	S\$	408.10
TOTAL LOSS		S\$	1,276.50

Steve (LKK)
01/07/24
Without Prejudice
P/P
Resurvey After Spray
1 day