

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP INC.
Veron.

LIFE PIANO TECHNICAL PTE LTD
1557 KEPPEL RD #03-21A
SINGAPORE 089066

TAX INVOICE

Repair Code : CLM16514

Date in : 14/12/2024

Vehicle Num. : GBK1240K

Model : NISSAN NV200 DX 1.6 AUTO

Chassis/Eng# : VM20140013/HR16156761D

Contact : 98381954

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	485.90	✓ 485.90
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	37.20	✓ 74.40
REAR BUMPER SPONGE <i>Build</i>	1	94.00	✓ 94.00
REAR BUMPER TOW HOOK COVER <i>new</i>	1	16.00	+ 16.00
REAR END PANEL (INNER) <i>Dented</i>	1	576.00	✓ 576.00
REAR END PANEL (OUTER) <i>Dented</i>	1	119.70	✓ 119.70
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	70.00	✓ 70.00
REAR SPARE TYRE CARRIAGE <i>new</i>	1	297.30	+ 297.30
REAR SPARE TYRE CARRIAGE BRACKET <i>new</i>	1	69.30	+ 69.30
REAR TAILGATE <i>Dented</i>	1	1635.00	✓ 1,635.00
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	64.90	✓ 64.90
REAR TAILGATE 'NV200' EMBLEM <i>new</i>	1	64.90	✓ 64.90
REAR TAILGATE 'VANETTE' EMBLEM <i>new</i>	1	94.50	- 94.50
REAR TAILGATE DAMPER L/R <i>new</i>	2	138.00	+ 276.00
REAR TAILGATE HINGES L/R <i>new</i>	2	52.00	+ 104.00
REAR TAILGATE INNER AUTO LOCK CONTROL ASSY <i>Build</i>	1	325.00	✓ 325.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	20.00	+ 40.00
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	298.00	✓ 298.00

*** This is a computer-generated document which requires no signature. ***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LIFE PIANO TECHNICAL PTE LTD
 1557 KEPPEL RD #03-21A
 SINGAPORE 089066

TAX INVOICE

Repair Code : CLM16514

Date in : 14/12/2024

Vehicle Num. : GBK1240K

Model : NISSAN NV200 DX 1.6 AUTO

Chassis/Eng# : VM20140013/HR16156761D

Contact : 98381954

REAR TAILGATE LOCK STRIKER	<i>Not in</i>	1	35.00	+	35.00
REAR TAILGATE MECHANISM LOCK	<i>Jammed</i>	1	288.90	✓	288.90
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>Not in</i>	2	25.00	+	50.00
REAR TAILGATE OUTER HANDLE	<i>rust</i>	1	352.00	2	352.00
REAR TAILGATE WEATHER STRIP	<i>Not</i>	1	88.40	2	88.40
REAR TAILLAMP L/R	<i>Not</i>	2	258.00	2	516.00

Subtotal before discount

6,035.20

Percentage discount 10%

603.52

Sub-total 1

5,431.68

REAR BUMPER CLIPS - SET	<i>Not</i>	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR - SET	<i>Not</i>	1	280.00	200	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Not</i>	1	40.00	20	40.00
REAR TAILGATE '70KM' STICKER	<i>Not</i>	1	25.00	15	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>Not</i>	1	50.00	30	50.00
REAR TAILGATE NUMBER PLATE	<i>Not in</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER	<i>Not in</i>	1	50.00	+	50.00
REAR TAILGATE WINDSCREEN SEAL	<i>Not</i>	1	80.00	40	80.00
REAR TAILGATE WINDSCREEN SEALANT	<i>Not</i>	1	80.00	40	80.00

*** This is a computer-generated document which requires no signature.***

page 2

Ren floor panel *deducted* *\$ 1325.00* *Local Reps*
Repair *\$ 300*

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIFE PIANO TECHNICAL PTE LTD
1557 KEPPEL RD #03-21A
SINGAPORE 089066

Contact : 98381954

TAX INVOICE

Repair Code : CLM16514

Date in : 14/12/2024

Vehicle Num. : GBK1240K

Model : NISSAN NV200 DX 1.6 AUTO

Chassis/Eng# : VM20140013/HR16156761D

Subtotal before discount	680.00
Percentage discount 0%	0.00
Sub-total 2	680.00
Parts-total	6,111.68

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.


To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,730.00
Parts & Labour Total	8,841.68

*** This is a computer-generated document which requires no signature.***

page 3



Adrian Cj
h/s 17/12/24
07
Total: 7287.84
h/s: 5.8K ✓