



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

17/12/2024

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claim Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBA 2625 E
MODEL: TOYOTA DYNA
DATE OF ACCIDENT: 13/12/2024
YOUR INSURED VEHICLE NO. SBS 6081 C

1 pc	Tailgate	\$	1,800.00	N
1 pc	RH side gate		1,900.00	N
1 pc	TOYOTA logo		180.00	N
1 pc	Rear number plate bracket		80.00	N
1 pc	Rear steping board		120.00	N
1 pc	13 PAX sticker		25.00	SN
1 pc	70 Km/h sticker		25.00	SN
1 pc	Dyna logo		35.00	SN
1 pc	Rear number plate		35.00	SN
		\$	4,200.00	

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

600.00
500.00
<u>5,300.00</u>

Yours faithfully,

Palindya