

BIFROST AUTO PTE LTD

REPAIR ESTIMATEDATE: 1-Jul-24INSURANCE: IIIMODEL: TOYOTA PRIUS G5VEHICLE NO.: SHD 6667 X

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>Denal / Kt</i>	1	\$ 1,577.24	\$1,577.24
REAR TRUNK LID LOCK <i>src</i>	1	\$ 641.06	\$641.06
REAR TRUNK LID LOCK COVER <i>HH</i>	1	\$ 129.80	\$ 129.80
REAR TRUNK LID LOCK SWITCH <i>HH</i>	1	\$ 468.90	\$ 468.90
REAR TRUNK LID COVER TRIM BOARD <i>HH</i>	1	\$ 303.10	\$303.10
REAR TRUNK LID RUBBER <i>dyneal</i>	1	\$ 511.28	\$511.28
REAR TRUNK LID LAMP G5 <i>HH</i>	1	\$ 891.52	\$891.52
REAR TRUNK LID GLASS (BLACK COLOR) <i>HH</i>	1	\$ 2,197.58	\$2,197.58
BOARD ASSY, BACK DOOR TRIM <i>HH</i>	1	\$ 356.16	\$356.16
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>HH</i>	1	\$ 1,845.58	\$1,845.58
REAR TRUNK LID LOGO (PRIUS) <i>src</i>	1	\$ 85.12	\$85.12
REAR TRUNK LID LOGO (HYBRID) <i>src</i>	1	\$ 73.36	\$73.36
REAR TRUNK LID LOGO (TOYOTA STAR) <i>src</i>	1	\$ 74.06	\$74.06
THIRD BRAKE LIGHT <i>HH</i>	1	\$ 552.58	\$552.58
REAR TRUNK LID STRIKER <i>HH</i>	1	\$ 138.18	\$138.18
REAR TRUNK LID HINGE (LH/RH) <i>HH</i>	2	\$ 265.30	\$530.60
REAR TRUNK LID ABSORBER (LH/RH) <i>HH</i>	2	\$ 402.50	\$805.00
REAR TRUNK LID ABSORBER BRACKET (LH/RH) <i>HH</i>	2	\$ 179.06	\$358.12
REAR TRUNK LID STOPPER (LH/RH) <i>HH</i>	2	\$ 118.72	\$237.44
SPOILERSUB-ASSY, REAR <i>HH</i>	1	\$ 1,335.18	\$1,335.18
REAR BUMPER <i>Denal</i>	1	\$ 642.04	\$642.04
REAR BUMPER RE-INFORCEMENT <i>HH</i>	1	\$ 446.32	\$446.32
REAR BUMPER UNDER COVER <i>HH</i>	1	\$ 773.64	\$773.64
REAR BUMPER SIDE RETAINER <i>HH</i>	2	\$ 157.78	\$315.56

REAR BUMPER UNDER CENTRE COVER <i>HH</i>	1	\$ 773.64	\$773.64	X
REAR BUMPER TOWING COVER <i>HH</i>	1	\$ 115.78	\$115.78	X
REAR BUMPER CLIPS <i>Hu</i>	1	\$ 30.80	\$30.80	✓
REAR BUMPER SIDE CLIP <i>HH</i>	2	\$ 35.00	\$70.00	X
ARM SUB-ASSY, REAR BUMPER, RH <i>HH</i>	1	\$ 195.44	\$195.44	X
REAR BUMPER UNDER SIDE COVER (RH) <i>HH</i>	1	\$ 324.80	\$324.80	X
RETAINER, REAR BUMPER, SIDE, RH <i>HH</i>	1	\$ 132.72	\$132.72	X
RETAINER, REAR BUMPER, UPPER SIDE (LH/RH) <i>HH</i>	2	\$ 42.98	\$85.96	X
RETAINER, REAR BUMPER, SIDE, LH <i>HH</i>	1	\$ 132.72	\$132.72	X
REAR BUMPER UNDER SIDE COVER (LH) <i>HH</i>	1	\$ 324.80	\$324.80	X
ARM SUB-ASSY, REAR BUMPER, LH <i>HH</i>	1	\$ 195.44	\$195.44	X
REAR BUMPER LOWER COVER GARNISH G5 <i>Dental</i>	1	\$ 963.63	\$963.63	✓
TAIL LAMP ASSY (UPPER) G5 <i>HH</i>	2	\$ 942.90	\$1,885.80	X
TAIL LAMP ASSY (LOWER) G5 <i>HH</i>	2	\$ 860.58	\$1,721.16	X
TAIL LAMP QUARTER PANEL <i>HH</i>	2	\$ 302.40	\$604.80	X
REAR END PANEL GARNISH COVER <i>HH</i>	1	\$ 138.90	\$138.90	X
TAIL LAMP SIDE COVER <i>HH</i>	2	\$ 358.40	\$716.80	X
REAR END PANEL <i>Dental</i>	1	\$ 842.94	\$842.94	✓
REAR END PANEL GARNISH <i>HH</i>	1	\$ 294.80	\$294.80	X
REAR SPARE TYRE PANEL <i>HH</i>	1	\$ 960.80	\$960.80	X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>SVC</i>	1	\$ 668.90	\$668.90	X
REAR FIBER TOOL BOX TRIM <i>HH</i>	1	\$ 557.20	\$557.20	X
SPARE TYRE LOCK NUT <i>HH</i>	1	\$ 123.76	\$123.76	X
REAR WINDSCREEN GLASS W/ MOULDING <i>HH</i>	1	\$ 2,489.62	\$2,489.62	X
REAR WINDSCREEN SEALANT <i>HH</i>	1	\$ 64.40	\$64.40	X
			\$29,705.03	
SUB TOTAL <i>5014.25</i>				
LESS 20% <i>25%</i> <i>3760.68</i>			\$5,941.01	
DISCOUNTED TOTAL			\$23,764.02	
REAR TRUNK LOWER W/S MOULDING <i>HH</i> SN	1	\$180.00	\$180.00	X
REAR LOWER W/S SEALANT <i>Hu</i> SN	1	\$46.00	\$46.00	✓
REAR NO. PLATE WITH TRIM COVER <i>HH</i> SN	1	\$ 140.00	\$140.00	X
REAR TRUNK LID APPS STICKER <i>Hu</i> SN	1	\$ 56.00	\$56.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>Hu</i> SN	1	\$ 84.00	\$84.00	✓

REAR BUMPER REVERSE SENSOR <i>Don</i>	SN	1	\$ 189.98	\$189.98	✓
REAR BUMPER RUBBER MAT <i>defunct</i>	SN	1	\$ 70.00	\$70.00	50/-
SUB TOTAL				\$765.98	
Labour Charge					
Panel Beating		1	\$ 1,800.00	\$1,800.00	600/-
Spray Painting Charge		1	\$ 1,400.00	\$1,400.00	600/-
Wiring Charge		1	\$ 100.00	\$100.00	20/-
Tuff Kote		1	\$ 100.00	\$100.00	20/-
Towing Charge		1	\$ 80.00	\$80.00	42
Remove/Refix Cushion & Upholstery Rear		1	\$ 150.00	\$150.00	60/-
Remove/Refix Rear Windscreen Glass		2	\$ 120.00	\$240.00	80/-
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	\$550.00	42
TOTAL LABOUR				\$4,420.00	
ESTIMATE TOTAL				\$28,950.00	
prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

02/07/2024 @ 1030m
NA Abdul

5566-66

4/s 4,450/-

2/sum

[Signature] bds.

2KK Abdul

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

Vehicle Details

Vehicle No.:

SHD6667X

Vehicle to be Exported:

No

Intended Deregistration Date:

31 Jul 2024

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)(2WD)

Primary Colour:

Blue

Manufacturing Year:

2022

Engine No.:

2ZR2R16797

Chassis No.:

JTDKB3FU903096594

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,880.00

Original Registration Date:

29 Apr 2022

First Registration Date:

29 Apr 2022

Transfer Count:

0

Actual ARF Paid:

\$7,132.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

28 Apr 2030

PARF Rebate Amount:

\$5,349.00

Intended COE Rebate Details

COE Expiry Date:

28 Apr 2030

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$50,576.00

COE Rebate Amount:

\$36,316.00

Total Rebate Amount:

\$41,665.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Jul 2024

OK