



Final Report

Estimate No. : **b1 72121**
 Date Estimated : **14/12/2024**
 Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- ESTIMATE REPAIR FOR -

TEE PAK CHUAN
BLK 38 ANCHORVALE LANE
#13-35

SINGAPORE 544593

- ACCOUNT - **135**

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SNK6178H	WBA62EG0305V93263	27/04/2023	X1 sDrive16i	29869

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper bottom trim, rear bumper bottom cover, rear bumper LH trim include making good the rear bumper panel and carrying out other necessary repairs caused by the accident	850.00		850.00
To spray paint rear bumper	1,038.00		1,038.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
Sundries	40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER BOTTOM TRIM (M)	207.70	1.00	0.00	207.70
REAR BUMPER BOTTOM COVER (M)	364.35	1.00	0.00	364.35
REAR BUMPER LH TRIM (M)	53.70	1.00	0.00	53.70
# EXPANDING RIVET BLACK	1.50	10.00	0.00	15.00

SUPPLEMENTARY ITEMS

Total Labour :	2,282.00
Total Parts :	640.75
Total Labour & Parts (before GST) :	2,922.75
Deduction for Excess :	
Total Repair Costs less Excess:	2,922.75
GST @9%:	263.05
Grand Total :	3,185.80

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
 Co Reg No. 197401559W

