



Elite AM Pte Ltd

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01
Singapore 768159
Tel: 67545101

DATE: 17-12-2024

REPAIR ESTIMATE

VEHICLE: SKZ8123J
MODEL: Toyota Alphard

S/n	Description of part	Qty	Estimate
1	Front bumper ✓	1	300.00
2	Front bumper clip set ✓	1	30.00
3	Front bumper retainer LH/RH ?	2	100.00
4	Front bumper towing cover LH/RH ?	2	30.00
5	Front reinforcement ?	1	220.00
6	Front reinforcement sponge ?	1	60.00
7	Front radiator grill ✓	1	400.00
8	Front radiator grill cover LH/RH ?	2	50.00
9	Front emblem ✓	1	120.00
10	Headlamp LH/RH ✓	2	4,800.00
11	Headlamp garnish LH/RH ?	2	80.00
12	Front bonnet R	1	320.00
13	Front bonnet seal X	1	40.00
14	Front bonnet hinge LH/RH ✓	2	100.00
15	Front bonnet insulator clip set ✓	1	30.00
16	Front bonnet moulding - chrome ✓	1	180.00
17	Front bonnet lock mechanism ?	1	50.00
18	Front fender LH/RH R	2	900.00
19	Front fender inner liner LH/RH X	1	130.00
20	Fender inner liner clip set X	2	60.00
21	Front fender bracket LH/RH X	2	90.00
22	Front radiator support top R	1	240.00
23	Front radiator support bottom ?	1	120.00
24	Radiator air guide LH/RH ?	2	100.00
Sub-total 1			\$8,550.00
Cost plus 10%			\$9,405.00

Special Nett Item			
25	Front number plate ✓	1	35 \$50.00
26	Front parking sensors ?	1	\$200.00
Sub-total 2			\$250.00
Total parts:			\$9,655.00



Elite AM Pte Ltd

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01
Singapore 768159
Tel: 67545101

Labour		<i>Qty</i> <i>Barret/spr/holes</i>	
27	To straighten and panel beating front frame members.	1	<i>540</i> 1,000.00
28	To putty, re-spray painting and polish affected areas.	1	<i>800</i> 1,200.00
29	To install new parking sensor	<i>1</i>	<i>50</i> 180.00
30	To calibrate parking sensor and forward collision sensors after repair	1	150.00
Labour total			\$2,530.00
Parts & Labour total			\$12,185.00