



Elite AM Pte Ltd

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01
Singapore 768159
Tel: 67545101

Not Not work

1/1 Sep 8

Running After Paint

Ex TBA

4 days

Kennerth
96910663

DATE: 17-12-2024

REPAIR ESTIMATE

VEHICLE: SKZ8123J
MODEL: Toyota Alphard

S/n	Description of part	Qty	Estimate
1	Front bumper	1	CM 300.00 ✓
2	Front bumper clip set	1	h 30.00 ✓
3	Front bumper retainer LH/RH	2	100.00 ✓
4	Front bumper towing cover LH/RH	2	h 30.00 X
5	Front reinforcement	1	R 220.00 X
6	Front reinforcement sponge	1	h 60.00 X
7	Front radiator grill	1	CM 400.00 ✓
8	Front radiator grill cover LH/RH	2	h 50.00 X
9	Front emblem	1	mit 120.00 ✓
10	Headlamp LH/RH	2	mgum 4,800.00 ✓
11	Headlamp garnish LH/RH	2	h 80.00 X
12	Front bonnet	1	R 320.00 X
13	Front bonnet seal	1	h 40.00 X
14	Front bonnet hinge LH/RH	2	R 100.00 X
15	Front bonnet insulator clip set	1	h 30.00 X
16	Front bonnet moulding - chrome	1	mgum 180.00 ✓
17	Front bonnet lock mechanism	1	R 50.00 X
18	Front fender LH/RH	2	R 900.00 X
19	Front fender inner liner LH/RH	1	h 130.00 X
20	Fender inner liner clip set	2	h 60.00 X
21	Front fender bracket LH/RH	2	R 90.00 X
22	Front radiator support top	1	R 240.00 X
23	Front radiator support bottom	1	R 120.00 X
24	Radiator air guide LH/RH	2	h 100.00 X
Sub-total 1			\$8,550.00
Cost plus 10%			\$9,405.00

Special Nett Item			
25	Front number plate	1	h \$50.00 X
26	Front parking sensors	1	h \$200.00 X
Sub-total 2			\$250.00
Total parts:			\$9,655.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Elite AM Pte Ltd**

No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01
Singapore 768159
Tel: 67545101

	Labour		
27	To straighten and panel beating front frame members.	1	1,000.00
28	To putty, re-spray painting and polish affected areas.	1	1,200.00
29	To install new parking sensor	1	180.00
30	To calibrate parking sensor and forward collision sensors after repair	1	150.00
Labour total			\$2,530.00
Parts & Labour total			\$12,185.00

500/
400/
501.
X