

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Lee Boon Precision Engineering Service
53 Normanton Park
Singapore 117282

Vehicle N: GBM 6554 L
Make/Mo : Nissan NV200
Year : 2023

Not Authorized
L1 By \$650.00
Repair After Paint
7 day

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	1819		By	\$2,135.60	✓
1 pc	Rear tail-gate inner trim board			sn	\$455.20	X
1 pc	Rear tail-gate inner lock	210.30		nd	\$287.60	✓
1 pc	Rear tail-gate outer handle			sn	\$255.70	X
2 pcs	Rear no plate lamp			sn	\$90.20	X
1 pc	Rear tail-gate emblem "NV200"			na	\$55.10	—
1 pc	Rear tail-gate emblem "LOGO"			na	\$65.20	—
1 pc	Rear tail-gate emblem - Badge			na	\$45.60	—
1 pc	Rear tail-gate glass moulding			nsp	\$105.20	X
1 pc	Rear o/s tail-lamp assy			cut/mount	\$305.60	✓
1 pc	Rear end panel			By	\$284.60	✓
1 pc	Rear end panel inner garnish			cut	\$145.60	✓
1 pc	Rear boot floor panel			By L R	\$2,025.60	sp5000
1 pc	Rear boot floor panel top cover board			nd	\$487.30	✓
1 pc	Rear boot floor panel top floor mat			reborn	\$387.00	✓
1 pc	Rear boot rubber			dis/lay	\$265.70	✓
1 pc	Rear bumper			By	\$584.70	✓
1 pc	Rear bumper sponge			By	\$145.60	✓
2 pcs	Rear bumper side retainer			sn	\$150.20	X
					\$8,277.30	
					Less 10 %	\$827.73
						\$7,449.57

S Nett

1 pc	Rear tail-gate glass sealant
2 pcs	Rear reverse sensor
1 pc	Rear n/s tail-gate sticker "70 kmph"

na	\$35.00	✓
scel	\$200.00	✓
na	\$15.00	✓
	\$245.00	

balance c/f \$7,699.57

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GBM 6554 L

balance b/f

\$7,699.57

Labour Charges

Remove/renew the above parts including knocking, welding & cutting

\$1,800.00 *1400/-*

To putty and spray paint

\$1,500.00 *900/-*

Check & reconnect wiring.

\$30.00 *20/-*

To respray anti-rust proofing treatment

\$150.00 *60/-*

Remove/refit rear tail-gate glass

\$120.00 *✓*

Remove/refit both rear tail-gate mechanism to new door

\$180.00 *60/-*

Total

\$11,479.57